Register entry, as of 29 October 2026 Listed for sale Record ID 09a208fe09b6

2023 Mercedes-Benz AMG GT AMG GT63

4.0 L, 8 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1K	7X8JB	3	P	A	053603
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz Cars	AMG GT · 4.0 L	Computes	2023	Germany	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	4.0 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	AMG GT	Drive	Not in the decode
Trim	AMG GT63	Maker	Mercedes-Benz Cars
Body	Sedan	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/amg-gt/2023

6 recalls listed by Transport Canada for this model year

Electrical — 2024615 — 18 Oct 2024

Issue: On certain vehicles equipped with 4-wheel drive (4Matic), the transmission wiring harness may not be routed correctly. As a result, water could enter the wiring harness connector and cause a short circuit. Note: This recall is an expansion of Transport Canada recall no. 2024-342. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the transmission wiring harness.

Electrical — 2024105 — 16 Feb 2024

Issue: On certain vehicles, the 80 A fuse may not have been manufactured properly. As a result, the fuse could overheat and fail. If this happens, there could be a sudden loss of power to the wheels. This could also cause the instrument cluster not to work. Safety Risk: A fuse and wiring that overheats can create the risk of a fire. A sudden loss of power to the wheels could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the main fuse box.

Electrical — 2024081 — 9 Feb 2024

Issue: On certain vehicles, the bolt for the 48 V ground connection may not have been tightened properly. As a result, the wiring could overheat and melt. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the ground connection.

Fuel system

2023672 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Other

2023448 11 Aug 2023

Issue: On certain vehicles, the exit warning feature may not work properly. As a result, a person leaving the vehicle may not get a warning while opening their door in certain traffic situations where another vehicle is approaching from behind. Safety Risk: Opening a door while a vehicle is approaching from behind could create an increased risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to update the multimode radar software.

Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $157,777[4], $28,891 over the median of $128,886[3].



Lowest ask	$99,995
Middle half	$114,440 – $143,332
Median ask	$128,886
This car	$157,777

Same model year · 2 live listings · as of 29 Oct 2026

§4 EVENTS

2023	Model year 2023[1] Assembly plant Germany
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
11 Aug 2023	Transport Canada recall 2023448[2] Issued for the model year · Other
15 Dec 2023	Transport Canada recall 2023672[2] Issued for the model year · Fuel system
9 Feb 2024	Transport Canada recall 2024081[2] Issued for the model year · Electrical

16 Feb 2024	Transport Canada recall 2024105[2] Issued for the model year · Electrical
18 Oct 2024	Transport Canada recall 2024615[2] Issued for the model year · Electrical
24 Oct 2026	Listed for sale, Scarborough, ON[4] Manhattan Motorcars · asking $157,777
29 Oct 2026	Listing last updated[4] asking $157,777

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 2 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.