Register entry, as of 29 October 2026 Listed for sale Record ID 9c882b9862d8

2023 Mercedes-Benz SL-Class AMG SL63

4.0 L, 8 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1K	VK8BB	9	P	F	016756
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Cars	SL-Class · 4.0 L	Computes	2023	Germany	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	4.0 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	SL-Class	Drive	Not in the decode
Trim	AMG SL63	Maker	Mercedes-Benz Cars
Body	Convertible	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/sl-class/2023

5 recalls listed by Transport Canada for this model year

Electrical — 2025213 — 17 Apr 2025

Issue: On certain vehicles, the recall repairs completed by a Mercedes-Benz dealer during recall 8297011 (Transport Canada recall no. 2024-105) may not have been done correctly. As a result, a second repair is required. On certain vehicles, the 80 A fuse may not have been manufactured properly. As a result, the fuse could overheat and fail. If this happens, there could be a sudden loss of power to the wheels. This could also cause the instrument cluster not to work. Safety Risk: A fuse and wiring that overheats can create the risk of a fire. A sudden loss of power to the wheels could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the main fuse box.

Electrical — 2024105 — 16 Feb 2024

Issue: On certain vehicles, the 80 A fuse may not have been manufactured properly. As a result, the fuse could overheat and fail. If this happens, there could be a sudden loss of power to the wheels. This could also cause the instrument cluster not to work. Safety Risk: A fuse and wiring that overheats can create the risk of a fire. A sudden loss of power to the wheels could increase the risk of a crash. Warnings, tell-tales and gauges that don't display could also increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the main fuse box.

Fuel system — 2023672 — 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Electrical

2023542 6 Oct 2023

Issue: On certain vehicles, the starter wiring harness may have been routed incorrectly. As a result, the wiring could be damaged by contact with the driveshaft. If this happens, the wiring could short circuit and melt or cause a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Wiring that overheats and melts could create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect the starter wiring harness, and re-route it as necessary. If the wiring harness is damaged, the dealer will repair or replace it, as necessary.

Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $164,399[4], $1,239 under the median of $165,638[3].

Lowest ask	$164,399
Middle half	$165,018 – $166,258
Median ask	$165,638
This car	$164,399

Same model year · 2 live listings · as of 29 Oct 2026

§4 EVENTS

2023	Model year 2023[1] Assembly plant Germany
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
6 Oct 2023	Transport Canada recall 2023542[2] Issued for the model year · Electrical
15 Dec 2023	Transport Canada recall 2023672[2] Issued for the model year · Fuel system
16 Feb 2024	Transport Canada recall 2024105[2] Issued for the model year · Electrical
17 Apr 2025	Transport Canada recall 2025213[2] Issued for the model year · Electrical
10 Oct 2026	Listed for sale, Boucherville, QC[4] Mercedes-Benz De Boucherville · asking $164,399

29 Oct 2026	Listing last updated[4] asking $164,399

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 2 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.