Register entry, as of 29 October 2026 Listed for sale Record ID 7774b96c8267

2021 Mercedes-Benz C-Class AMG C43

3.0 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1K	WJ6EB	1	M	G	063003
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz Cars	C-Class · 3.0 L	Computes	2021	Germany	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	C-Class	Drive	Not in the decode
Trim	AMG C43	Maker	Mercedes-Benz Cars
Body	Coupe	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/c-class/2021

9 recalls listed by Transport Canada for this model year

Structure

2026364 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away. Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

Fuel system

2023672 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Visual system

2022177 12 Apr 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the rearview camera software.

Lights and instruments

2021415 5 Jul 2021

Issue: On certain vehicles, a label on the headlamp assembly may contain incorrect information for a service technician. As a result, the headlamps may not get adjusted correctly after a repair. This could cause glare and/or confusion for oncoming drivers. Note: This recall only affects certain vehicles equipped with LED headlamps. Safety Risk: Headlamps that cause glare or confusion for oncoming drivers could increase the risk of a crash. Corrective Action: Mercedez-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the headlamps.

Seats and restraints

2021340 1 Jun 2021

Issue: On certain C and E-Class convertible models, the head restraints on the rear seats may not have been properly assembled. As a result, the head restraints may not latch properly, and could move or detach from the seat in a crash. Safety Risk: Head restraints that move or detach in a crash could increase the risk of an injury. Corrective Action: Mercedes-Benz will contact owners by mail and instruct you to take your car to a dealer to inspect and replace the rear seat head restraints, as required. To reduce the safety risk, Mercedes-Benz recommends that you should remove the rear seat head restraints and not use the rear seats until the recall repairs are completed.

3 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/c-class/2021

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $43,898[4], $403 over the median of $43,495[3].

Lowest ask	$22,770
Middle half	$29,000 – $54,998
Median ask	$43,495
This car	$43,898

Same model year · 29 live listings · as of 29 Oct 2026

OTHER 2021 MERCEDES-BENZ C-CLASS LISTINGS [4]

Richmond, BC · 37,248 km	$84,995
Kelowna, BC · 50,142 km	$86,995
Winnipeg, MB · 78,451 km	$45,698
Québec, QC · 32,000 km	$34,995
Québec, QC · 71,000 km	$30,995
Toronto, ON · 147,000 km	$22,770

§4 EVENTS

2021	Model year 2021[1] Assembly plant Germany
1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064[2] Issued for the model year · Electrical
7 Apr 2021	Transport Canada recall 2021207[2] Issued for the model year · Airbag
1 Jun 2021	Transport Canada recall 2021340[2] Issued for the model year · Seats and restraints
5 Jul 2021	Transport Canada recall 2021415[2] Issued for the model year · Lights and instruments
12 Apr 2022	Transport Canada recall 2022177[2] Issued for the model year · Visual system
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
15 Dec 2023	Transport Canada recall 2023672[2] Issued for the model year · Fuel system
24 Jul 2026	Transport Canada recall 2026364[2] Issued for the model year · Structure
14 Oct 2026	Listed for sale, Vaughan, ON[4] Northline Motors Inc. · asking $43,898
29 Oct 2026	Listing last updated[4] asking $43,898

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 29 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.