Register entry, as of 29 October 2026 Listed for sale Record ID 3a778d4256c4

# 2022 Mercedes-Benz E-Class E350 4MATIC

2.0 L, 4 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| W1K | ZF8EB | 3 | N | B | 079874 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mercedes-Benz Cars | E-Class · 2.0 L | Computes | 2022 | Germany | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 2.0 L, 4 cylinders |
| Make | Mercedes-Benz | Fuel | Gasoline |
| Model | E-Class | Drive | AWD |
| Trim | E350 4MATIC | Maker | Mercedes-Benz Cars |
| Body | Sedan | Plant | Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/e-class/2022

**9** recalls listed by Transport Canada for this model year

### Electrical — 2024615 — 18 Oct 2024

Issue: On certain vehicles equipped with 4-wheel drive (4Matic), the transmission wiring harness may not be routed correctly. As a result, water could enter the wiring harness connector and cause a short circuit. Note: This recall is an expansion of Transport Canada recall no. 2024-342. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the transmission wiring harness.

### Electrical — 2024342 — 14 Jun 2024

Issue: On certain vehicles, the recall repairs completed by a Mercedes-Benz dealer during recall 5491309 (Transport Canada recall no. 2022-397) may not have been done correctly. As a result, a second repair is required. On certain vehicles equipped with 4-wheel drive (4Matic), the transmission wiring harness may not be routed correctly. As a result, water could enter the wiring harness connector and cause a short circuit. Note: This recall replaces Transport Canada recall no. 2022-397. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the transmission wiring harness.

### Electrical — 2024081 — 9 Feb 2024

Issue: On certain vehicles, the bolt for the 48 V ground connection may not have been tightened properly. As a result, the wiring could overheat and melt. Safety Risk: Wiring that overheats and melts can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, tighten the ground connection.

### Fuel system

2023672 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

### Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

### Electrical

2022547 29 Sep 2022

Issue: On certain vehicles, the 12 V battery (in the trunk) could move in a crash. As a result, the battery electrical connexions could detach. If this happens, the post-crash safety systems (like the emergency calling (eCall) system, electric seat adjustment, hazard warning lights, and automatic door unlocking) may not work. Safety Risk: Safety systems that don't work correctly could increase the risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to add a bracket to better secure the battery.

3 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/e-class/2022

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

## §3 VALUE [3]

This car asks $42,301[4], $9,694 under the median of $51,995[3].

| | |
|---|---|
| Lowest ask | $42,301 |
| Middle half | $49,219 – $67,900 |
| Median ask | $51,995 |
| This car | $42,301 |

Same model year · 18 live listings · as of 29 Oct 2026

### OTHER 2022 MERCEDES-BENZ E-CLASS LISTINGS [4]

| | |
|---|---|
| Edmonton, AB · 38,957 km | $66,900 |
| Edmonton, AB · 0 km | $67,900 |
| Montréal-Est, QC · 24,603 km | $79,990 |
| Kingston, ON · 62,534 km | $66,888 |
| Montréal Nord, QC · 97,827 km | $48,999 |
| Québec, QC · 69,995 km | $51,995 |

## §4 EVENTS

2022 Model year 2022[1]
Assembly plant Germany

| | |
|---|---|
| 25 Mar 2022 | Transport Canada recall 2022140[2]<br>Issued for the model year · Accessories |
| 20 May 2022 | Transport Canada recall 2022263[2]<br>Issued for the model year · Other |
| 22 Jul 2022 | Transport Canada recall 2022397[2]<br>Issued for the model year · Electrical |
| 29 Sep 2022 | Transport Canada recall 2022547[2]<br>Issued for the model year · Electrical |
| 23 Jun 2023 | Transport Canada recall 2023353[2]<br>Issued for the model year · Fuel system |
| 15 Dec 2023 | Transport Canada recall 2023672[2]<br>Issued for the model year · Fuel system |
| 9 Feb 2024 | Transport Canada recall 2024081[2]<br>Issued for the model year · Electrical |
| 14 Jun 2024 | Transport Canada recall 2024342[2]<br>Issued for the model year · Electrical |
| 18 Oct 2024 | Transport Canada recall 2024615[2]<br>Issued for the model year · Electrical |
| 2 Jun 2026 | Listed for sale, Mississauga, ON[4]<br>401 Dixie Hyundai · asking $42,301 |
| 29 Oct 2026 | Listing last updated[4]<br>asking $42,301 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 18 live listings, as of 29 Oct 2026
[4] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.