Register entry, as of 29 October 2026 Listed for sale Record ID c6871a7e7648

# 2020 Mercedes-Benz GLC-Class AMG GLC43

3.0 L, 6 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| W1N | 0G6EB | 5 | L | V | 243876 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mercedes-Benz, Ag | GLC-Class · 3.0 L | Computes | 2020 | Uusikaupunki | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 3.0 L, 6 cylinders |
| Make | Mercedes-Benz | Fuel | Gasoline |
| Model | GLC-Class | Drive | Not in the decode |
| Trim | AMG GLC43 | Maker | MERCEDES-BENZ, AG |
| Body | Sport Utility Vehicle | Plant | Uusikaupunki, Finland |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/glc-class/2020

**20** recalls listed by Transport Canada for this model year

### Structure — 2026364 — 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away. Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

### Lights and instruments — 2024064 — 2 Feb 2024

Issue: On certain vehicles, the headlamps were not adjusted properly at the factory. Safety Risk: Headlamps that aren't adjusted properly could cause reduced visibility and/or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect the headlamps, and adjust them as necessary.

### Structure — 2023673 — 15 Dec 2023

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Note: This is an expansion of Transport Canada recall 2021-170. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the front roof panel.

### Powertrain

2022372 8 Jul 2022

Issue: On certain vehicles, the transmission wiring harness may have been routed incorrectly. As a result, the wiring could be damaged by contact with the front driveshaft. If this happens, there could be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the transmission wiring harness, and replace it if necessary.

### Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

### Visual system

2022177 12 Apr 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the rearview camera software.

14 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/glc-class/2020

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

## §3 VALUE [3]

This car asks $34,587[4], $4,687 over the median of $29,900[3].

| | |
|---|---|
| Lowest ask | $22,888 |
| Middle half | $26,997 – $33,940 |
| Median ask | $29,900 |
| This car | $34,587 |

Same model year · 51 live listings · as of 29 Oct 2026

### OTHER 2020 MERCEDES-BENZ GLC-CLASS LISTINGS [4]

| | |
|---|---|
| London, ON · 77,000 km | $38,991 |
| Richmond, BC · 82,031 km | $26,995 |
| North York, ON · 41,190 km | $29,995 |
| Burlington, ON · 145,300 km | $22,888 |
| North York, ON · 123,435 km | $24,985 |
| Oakville, ON · 96,803 km | $37,499 |

## §4 EVENTS

2020 Model year 2020[1]
Assembly plant Uusikaupunki, Finland

| | |
|---|---|
| 2 Oct 2019 | Transport Canada recall 2019484[2]<br>Issued for the model year · Airbag |
| 7 Feb 2020 | Transport Canada recall 2020046[2]<br>Issued for the model year · Electrical |
| 9 Jun 2020 | Transport Canada recall 2020253[2]<br>Issued for the model year · Seats and restraints |
| 22 Jun 2020 | Transport Canada recall 2020282[2]<br>Issued for the model year · Engine |
| 6 Jul 2020 | Transport Canada recall 2020307[2]<br>Issued for the model year · Brakes |
| 27 Oct 2020 | Transport Canada recall 2020512[2]<br>Issued for the model year · Steering |
| 12 Dec 2020 | Transport Canada recall 2020614[2]<br>Issued for the model year · Electrical |
| 1 Feb 2021 | Transport Canada recall 2021041[2]<br>Issued for the model year · Accessories |
| 12 Feb 2021 | Transport Canada recall 2021064[2]<br>Issued for the model year · Electrical |
| 3 Mar 2021 | Transport Canada recall 2021112[2]<br>Issued for the model year · Other |
| 22 Mar 2021 | Transport Canada recall 2021170[2]<br>Issued for the model year · Structure |
| 14 May 2021 | Transport Canada recall 2021291[2]<br>Issued for the model year · Visual system |
| 13 Jul 2021 | Transport Canada recall 2021431[2]<br>Issued for the model year · Airbag |
| 13 Dec 2021 | Transport Canada recall 2021755[2]<br>Issued for the model year · Fuel system |
| 12 Apr 2022 | Transport Canada recall 2022177[2]<br>Issued for the model year · Visual system |
| 20 May 2022 | Transport Canada recall 2022263[2]<br>Issued for the model year · Other |
| 8 Jul 2022 | Transport Canada recall 2022372[2]<br>Issued for the model year · Powertrain |
| 15 Dec 2023 | Transport Canada recall 2023673[2]<br>Issued for the model year · Structure |
| 2 Feb 2024 | Transport Canada recall 2024064[2]<br>Issued for the model year · Lights and instruments |

| | |
|---|---|
| 24 Jul 2026 | Transport Canada recall 2026364[2]<br>Issued for the model year · Structure |
| 25 Oct 2026 | Listed for sale, Toronto, ON[4]<br>FAVORIT MOTORS · asking $34,587 |
| 28 Oct 2026 | Listing last updated[4]<br>asking $34,587 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 51 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.