Register entry, as of 25 November 2026 Listed for sale Record ID ef3f4917dcb8

# 2021 Mercedes-Benz GLC-Class GLC300-4M

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| W1N | 0G8EB | 8 | M | V | 319412 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mercedes-Benz, Ag | GLC-Class · 2.0 L | Computes | 2021 | Uusuikaupunki | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 2.0 L, 4 cylinders |
| Make | Mercedes-Benz | Fuel | Gasoline |
| Model | GLC-Class | Drive | Not in the decode |
| Trim | GLC300-4M | Maker | MERCEDES-BENZ, AG |
| Body | Sport Utility Vehicle | Plant | Uusuikaupunki, Finland |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/glc-class/2021

**12** recalls listed by Transport Canada for this model year

### Structure

2026364 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away. Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

### Lights and instruments

2024064 2 Feb 2024

Issue: On certain vehicles, the headlamps were not adjusted properly at the factory. Safety Risk: Headlamps that aren't adjusted properly could cause reduced visibility and/or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect the headlamps, and adjust them as necessary.

### Fuel system

2023672 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

### Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

### Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

### Lights and instruments

2022184 14 Apr 2022


Issue: On certain vehicles, the headlamp connectors may not be water-tight. As a result, moisture could enter the headlamp and cause it to fail. Safety Risk: A headlamp that fails could reduce visibility and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the headlamps and their connectors. The headlamp(s) and connectors will be replaced, if necessary.

6 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/glc-class/2021

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply. Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

## §3 VALUE [3]

This car asks $29,898[4], the median[3].




| | |
|---|---|
| Lowest ask | $24,980 |
| Middle half | $27,993 – $32,992 |
| Median ask | $29,898 |
| This car | $29,898 |

Same configuration · 35 live listings · as of 24 Nov 2026

OTHER 2021 MERCEDES-BENZ GLC-CLASS LISTINGS [4]

| | |
|---|---|
| Mirabel, QC · 78,865 km | $39,295 |
| Saskatoon, SK · 118,085 km | $29,011 |
| Blainville, QC · 93,311 km | $26,992 |
| Vaughan, ON · 58,414 km | $31,988 |
| Calgary, AB · 73,531 km | $29,988 |
| Sainte-Rose, QC · 84,000 km | $39,995 |

## §4 EVENTS

2021 Model year 2021[1]
Assembly plant Uusuikaupunki, Finland

| | |
|---|---|
| 1 Feb 2021 | **Transport Canada recall 2021041**[2]<br>Issued for the model year · Accessories |
| 12 Feb 2021 | **Transport Canada recall 2021064**[2]<br>Issued for the model year · Electrical |
| 8 Mar 2021 | **Transport Canada recall 2021125**[2]<br>Issued for the model year · Engine |
| 7 Apr 2021 | **Transport Canada recall 2021207**[2]<br>Issued for the model year · Airbag |
| 14 May 2021 | **Transport Canada recall 2021291**[2]<br>Issued for the model year · Visual system |
| 12 Apr 2022 | **Transport Canada recall 2022177**[2]<br>Issued for the model year · Visual system |
| 14 Apr 2022 | **Transport Canada recall 2022184**[2]<br>Issued for the model year · Lights and instruments |
| 20 May 2022 | **Transport Canada recall 2022263**[2]<br>Issued for the model year · Other |
| 23 Jun 2023 | **Transport Canada recall 2023353**[2]<br>Issued for the model year · Fuel system |
| 15 Dec 2023 | **Transport Canada recall 2023672**[2]<br>Issued for the model year · Fuel system |
| 2 Feb 2024 | **Transport Canada recall 2024064**[2]<br>Issued for the model year · Lights and instruments |
| 24 Jul 2026 | **Transport Canada recall 2026364**[2]<br>Issued for the model year · Structure |
| 13 Nov 2026 | **Listed for sale, Vaughan, ON**[4]<br>Northline Motors Inc. · asking $29,898 |
| 25 Nov 2026 | **Listing last updated**[4]<br>asking $29,898 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same configuration, 35 live listings, as of 24 Nov 2026

[4] Live public dealer listings on Cardog, as of 25 Nov 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.