

Register entry, as of 29 October 2026

Listed for sale

Record ID ff9b3270eec7

# 2023 Mercedes-Benz GLB-Class GLB250 4MATIC

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

|                              |                                     |                     |                 |                            |                                |
|------------------------------|-------------------------------------|---------------------|-----------------|----------------------------|--------------------------------|
| <b>W1N</b>                   | <b>4M4HB</b>                        | <b>7</b>            | <b>P</b>        | <b>W</b>                   | <b>320094</b>                  |
| WMI 1-3<br>Mercedes-Benz, Ag | DESCRIPTOR 4-8<br>GLB-Class · 2.0 L | CHECK 9<br>Computes | YEAR 10<br>2023 | PLANT 11<br>Aguascalientes | SERIAL 12-17<br>Build sequence |

## §1 IDENTITY [1]

|            |                       |        |                        |
|------------|-----------------------|--------|------------------------|
| Model year | 2023                  | Engine | 2.0 L, 4 cylinders     |
| Make       | Mercedes-Benz         | Fuel   | Gasoline               |
| Model      | GLB-Class             | Drive  | AWD                    |
| Trim       | GLB250 4MATIC         | Maker  | MERCEDES-BENZ, AG      |
| Body       | Sport Utility Vehicle | Plant  | Aguascalientes, Mexico |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/mercedes-benz/glb-class/2023](https://cardog.app/tools/recalls/mercedes-benz/glb-class/2023)

### 1 recall listed by Transport Canada for this model year

#### Structure

2026364 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away.

Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.  
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

[www.mercedes-benz.ca/en/recalls](https://www.mercedes-benz.ca/en/recalls)

## §3 VALUE [3]

This car asks \$26,995<sup>[4]</sup>, \$6,152 under the median of \$33,147<sup>[3]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$26,579            |
| Middle half | \$30,241 – \$34,586 |
| Median ask  | \$33,147            |
| This car    | \$26,995            |

Same configuration · 22 live listings · as of 29 Oct 2026

## OTHER 2023 MERCEDES-BENZ GLB-CLASS LISTINGS [4]

|                               |          |
|-------------------------------|----------|
| Regina, SK · 16,928 km        | \$39,993 |
| Church Point, NS · 102,063 km | \$28,595 |
| Yarmouth, NS · 102,063 km     | \$28,595 |

## §4 EVENTS

|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 2023        | Model year 2023 <sup>[1]</sup><br>Assembly plant Aguascalientes, Mexico                     |
| 7 May 2026  | Listed for sale, Kitchener, ON <sup>[4]</sup><br>Tabangi Motors Kitchener · asking \$26,995 |
| 24 Jul 2026 | Transport Canada recall 2026364 <sup>[2]</sup><br>Issued for the model year · Structure     |
| 28 Oct 2026 | Listing last updated <sup>[4]</sup><br>asking \$26,995                                      |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

|                                                                 |                                                                                  |
|-----------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN              | [3] Cardog market quote, same configuration, 22 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 29 Oct 2026                     |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

