

Register entry, as of 28 October 2026

Listed for sale

Record ID 4e2d489e1633

2021 Mercedes-Benz GLB-Class AMG GLB35

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1N 4M5BB X M W 148007

WMI 1-3

Mercedes-Benz, Ag

DESCRIPTOR 4-8

GLB-Class · 2.0 L

CHECK 9

Computes

YEAR 10

2021

PLANT 11

Aguascalientes

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GLB-Class	Drive	Not in the decode
Trim	AMG GLB35	Maker	MERCEDES-BENZ, AG
Body	Sport Utility Vehicle	Plant	Aguascalientes, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/glb-class/2021

11 recalls listed by Transport Canada for this model year

Structure

2026364 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away. Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

Label

2023200 31 Mar 2023

Issue: On certain AMG models, the vehicle type printed on the compliance label is incorrect. The vehicle type should be "MPV/VTUM" instead of "PC/VT". Canadian regulations require the vehicle type to be identified on the compliance label. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. Mercedes-Benz has made changes to ensure that all new vehicles have the correct vehicle type printed on the compliance label.

Label

2023199 31 Mar 2023

Issue: On certain vehicles, the vehicle type printed on the compliance label is incorrect. The vehicle type should be "MPV/VTUM" instead of "PC/VT". Canadian regulations require the vehicle type to be identified on the compliance label. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. Mercedes-Benz has made changes to ensure that all new vehicles have the correct vehicle type printed on the compliance label.



Brakes

2022511 9 Sep 2022

Issue: On a small number of vehicles, the electronic stability program (ESP) control unit may have been damaged during assembly. As a result, water could leak into the control unit and cause a short circuit. If this happens, the vehicle stability control and antilock brake system (ABS) could turn off. Safety Risk: A short circuit could create the risk of a fire. A loss of vehicle stability control and/or ABS could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to replace the ESP control unit.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Lights and instruments

2022241 6 May 2022

Issue: On a small number of vehicles, the level sensor linkage on the rear axle might not have been installed correctly. As a result, the headlamp leveling system may not work properly. Safety Risk: Headlamps that are not adjusted properly can cause glare for oncoming drivers and could increase the risk of a crash. Corrective Action: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the level sensor linkage and ensure it is installed correctly.

5 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/glb-class/2021

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks \$35,899^[4], \$8,577 over the median of \$27,322^[3].



Lowest ask	\$22,995
Middle half	\$25,909 – \$29,220
Median ask	\$27,322
This car	\$35,899

Same model year · 18 live listings · as of 28 Oct 2026

OTHER 2021 MERCEDES-BENZ GLB-CLASS LISTINGS [4]

North York, ON · 57,164 km \$28,995

§4 EVENTS

2021	Model year 2021 ^[1] Assembly plant Aguascalientes, Mexico
12 Feb 2021	Transport Canada recall 2021064 ^[2] Issued for the model year · Electrical
14 May 2021	Transport Canada recall 2021291 ^[2] Issued for the model year · Visual system



5 Jul 2021	Transport Canada recall 2021415 ^[2] Issued for the model year · Lights and instruments
8 Nov 2021	Transport Canada recall 2021682 ^[2] Issued for the model year · Airbag
12 Apr 2022	Transport Canada recall 2022177 ^[2] Issued for the model year · Visual system
6 May 2022	Transport Canada recall 2022241 ^[2] Issued for the model year · Lights and instruments
20 May 2022	Transport Canada recall 2022263 ^[2] Issued for the model year · Other
9 Sep 2022	Transport Canada recall 2022511 ^[2] Issued for the model year · Brakes
31 Mar 2023	Transport Canada recall 2023200 ^[2] Issued for the model year · Label
31 Mar 2023	Transport Canada recall 2023199 ^[2] Issued for the model year · Label
24 Jul 2026	Transport Canada recall 2026364 ^[2] Issued for the model year · Structure
22 Oct 2026	Listed for sale, Boucherville, QC ^[4] Mercedes-Benz De Boucherville · asking \$35,899
28 Oct 2026	Listing last updated ^[4] asking \$35,899

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [3] Cardog market quote, same model year, 18 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

