

Register entry, as of 26 October 2026

Listed for sale

Record ID d17592de65fb

2024 Mercedes-Benz GLA-Class GLA250 4MATIC/GLA250 4-M Turbo

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1N 4N4HB 7 R J 601891

WMI 1-3

Mercedes-Benz, Ag

DESCRIPTOR 4-8

GLA-Class · 2.0 L

CHECK 9

Computes

YEAR 10

2024

PLANT 11

Germany

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2024	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GLA-Class	Drive	AWD
Trim	GLA250 4MATIC/GLA250 4-M Turbo	Maker	MERCEDES-BENZ, AG
Body	Sport Utility Vehicle	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/gla-class/2024

2 recalls listed by Transport Canada for this model year

Structure

2026364 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away.

Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

Lights and instruments

2025404 6 Aug 2025

Issue: On certain vehicles, the identification marking on the headlamps may be missing. As a result, the headlamps may not be able to be adjusted correctly during service. Safety Risk: Headlamps that aren't aimed correctly could cause reduced visibility and/or glare for oncoming drivers and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the headlamps.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.

Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls



§3 VALUE [3]

This car asks \$33,900^[4], \$4,548 under the median of \$38,448^[3].



Lowest ask	\$31,888
Middle half	\$33,104 – \$42,995
Median ask	\$38,448
This car	\$33,900

Same model year · 6 live listings · as of 26 Oct 2026

§4 EVENTS

2024	Model year 2024 ^[1] Assembly plant Germany
6 Aug 2025	Transport Canada recall 2025404 ^[2] Issued for the model year · Lights and instruments
24 Jul 2026	Transport Canada recall 2026364 ^[2] Issued for the model year · Structure
26 Oct 2026	Listed for sale, Edmonton, AB ^[4] Mercedes-Benz Heritage Valley · asking \$33,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[3] Cardog market quote, same model year, 6 live listings, as of 26 Oct 2026
[2] Transport Canada recall database, listed for the model year	[4] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

