Register entry, as of 28 October 2026 Listed for sale Record ID 6cd4f0d4c410

2021 Mercedes-Benz G-Class AMG G63

4.0 L, 8 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1N	YC7HJ	6	M	X	370486
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz, Ag	G-Class · 4.0 L	Computes	2021	Graz	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	4.0 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	G-Class	Drive	Not in the decode
Trim	AMG G63	Maker	MERCEDES-BENZ, AG
Body	Sport Utility Vehicle	Plant	Graz, Austria

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/g-class/2021

9 recalls listed by Transport Canada for this model year

Fuel system — 2023672 — 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Fuel system — 2023353 — 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Brakes — 2023076 — 17 Feb 2023

Issue: On certain vehicles, the front axle wiring harness could be damaged by contact with the auxiliary oil cooler. If this happens, the vehicle electronic stability program (ESP) and antilock brake system (ABS) may not work correctly. Safety Risk: Antilock brake (ABS) and vehicle stability control (ESP) systems that don't work correctly could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect, and if necessary, replace the front axle wiring harness. The dealer will also install a protective sleeve.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Seats and restraints

2021493 6 Aug 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

Structure

2021285 14 May 2021

Issue: On certain vehicles, the rear door locks may not latch properly. As a result, a rear door could open while driving. Also, if a person tries to forcefully open a rear door while the child safety lock is activated, the door lock could be damaged. If this happens, passengers may not be able to open the rear doors from inside the vehicle. Safety Risk: A door that opens while driving could create an increased risk of injury. A door that cannot be opened from inside the vehicle may make it difficult to get out in an emergency. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear door locks.

3 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/g-class/2021

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $180,995[4], $2,798 under the median of $183,793[3].



Lowest ask	$168,888
Middle half	$178,800 – $189,995
Median ask	$183,793
This car	$180,995

Same configuration · 13 live listings · as of 28 Oct 2026

OTHER 2021 MERCEDES-BENZ G-CLASS LISTINGS [4]

Sherwood Park, AB · 7,780 km	$249,900
Langley Twp, BC · 49,400 km	$179,900
Vaughan, ON · 13,098 km	$199,898
Calgary, AB · 77,135 km	$173,995
Toronto, ON · 0 km	$168,888
North York, ON · 49,928 km	$188,888

§4 EVENTS

2021	Model year 2021[1] Assembly plant Graz, Austria
1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064[2] Issued for the model year · Electrical
7 Apr 2021	Transport Canada recall 2021207[2] Issued for the model year · Airbag
14 May 2021	Transport Canada recall 2021285[2] Issued for the model year · Structure
6 Aug 2021	Transport Canada recall 2021493[2] Issued for the model year · Seats and restraints
20 May 2022	Transport Canada recall 2022263[2] Issued for the model year · Other
17 Feb 2023	Transport Canada recall 2023076[2] Issued for the model year · Brakes
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
15 Dec 2023	Transport Canada recall 2023672[2] Issued for the model year · Fuel system
21 Sep 2026	Listed for sale, Calgary, AB[4] Lone Star Mercedes-Benz · asking $180,995
25 Oct 2026	Listing last updated[4] asking $180,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same configuration, 13 live listings, as of 28 Oct 2026

[4] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.