Register entry, as of 29 October 2026 Listed for sale Record ID c48b833c3b24

2023 Mercedes-Benz Sprinter 907 (VS30)

2.0 L · 4x2 · Incomplete - Chassis Cab · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

W1X	9N33Y	X	P	N	246434
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz, Ag	Sprinter · 2.0 L	Computes	2023	Germany	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.0 L
Make	Mercedes-Benz	Fuel	Diesel
Model	Sprinter	Drive	4x2
Trim	907 (VS30)	Maker	MERCEDES-BENZ, AG
Body	Incomplete - Chassis Cab	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/sprinter/2023

3 recalls listed by Transport Canada for this model year

Suspension

2024395 5 Jul 2024

Issue: On certain vehicle, the U-bolts that attach the rear axle to the suspension may not have been manufactured properly. As a result, the axle could slide on the leaf spring. This could cause poor handling and lead to a loss of control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the leaf spring U-bolts.

Structure

2024233 19 Apr 2024

Issue: On certain vehicles, the reinforcements on the B-pillar(s) may not have been properly welded. As a result, the front seat belt height adjuster(s) could fail in a crash. Safety Risk: A seat belt that does not work properly could increase the risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, repair the B-pillar(s).

Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $69,895[5], $14,900 over the median of $54,995[4].



Lowest ask	$38,880
Middle half	$44,495 – $62,998
Median ask	$54,995
This car	$69,895

Same model year · 31 live listings · as of 28 Oct 2026

OTHER 2023 MERCEDES-BENZ SPRINTER LISTINGS [5]

Halifax, NS · 119,562 km	$65,990
Ste-Marie de Beauce, QC · 198 km	$59,800
Toronto, ON · 49,334 km	$48,999
Toronto, ON · 58,751 km	$46,999
Toronto, ON · 281,941 km	$39,999
Halifax, NS · 76,929 km	$57,990

§4 EVENTS

2023	Model year 2023[1] Assembly plant Germany
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
19 Apr 2024	Transport Canada recall 2024233[2] Issued for the model year · Structure
5 Jul 2024	Transport Canada recall 2024395[2] Issued for the model year · Suspension
15 Oct 2026	Listed for sale, Mirabel, QC[5] Mercedes-Benz de Blainville · asking $69,895
29 Oct 2026	Listing last updated[5] asking $69,895

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 31 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.