Register entry, as of 28 October 2026 Listed for sale Record ID c99430369fa9

2021 Mercedes-Benz Sprinter 907 (VS30)

2.2 L, 4 cylinders · 4x2 · Cargo Van · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

W1Y	4DBHY	7	M	T	047389
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz, Ag	Sprinter · 2.2 L	Computes	2021	Charleston	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.2 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Diesel
Model	Sprinter	Drive	4x2
Trim	907 (VS30)	Maker	MERCEDES-BENZ, AG
Body	Cargo Van	Plant	Charleston, South Carolina, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/sprinter/2021

11 recalls listed by Transport Canada for this model year

Structure

2023689 21 Dec 2023

Issue: On certain vehicles, the rear frame may be missing reinforcements. As a result, the frame could become damaged and cause a change vehicle stability. This problem could also cause the mounting points for the third-row seats to fail in a crash. Safety Risk: A change in vehicle stability could cause a loss of control and increase the risk of a crash. Additionally, a seat that moves or separates in a crash could increase the risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, repair the longitudinal frame members.

Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Lights and instruments

2023167 24 Mar 2023

Issue: On certain vehicles, a software problem could cause the instrument cluster not to work. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, indicator lamps, and warning messages. In addition, the warning sounds may not work. Safety Risk: Warnings and malfunction tell-tale information that does not display could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the instrument cluster software.

Powertrain

2022602 21 Oct 2022

Issue: In certain conditions, the vehicle could roll-away after placing the transmission in the "P" (Park) position if the parking brake is not set. Note: You should always follow the parking procedure in the owner's manual, and set the parking brake each time that you park. Safety Risk: A parked vehicle that rolls away could create a risk of a crash or an injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the software of various control units.

Visual system

2022214 27 Apr 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the rearview camera software.

Label

2022061 10 Feb 2022

Issue: The tire and loading information label on certain vehicles may list the wrong combined weight of occupants and cargo. As a result, you could overload the vehicle. This could cause excessive tire wear and lead to a tire failure. Safety Risk: A tire failure could cause a loss of control and result in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the tire and loading information label. Additionally, the dealer will inspect the tires for excessive wear due to this issue, and replace them if necessary.

5 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/sprinter/2021

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

United States: 18 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $28,500[5], $6,389 under the median of $34,889[4].

Lowest ask	$23,995
Middle half	$29,624 – $37,582
Median ask	$34,889
This car	$28,500

Same configuration · 12 live listings · as of 28 Oct 2026

OTHER 2021 MERCEDES-BENZ SPRINTER LISTINGS [5]

Toronto, ON · 148,077 km	$29,999
Saint-Sulpice, QC · 118,811 km	$36,995
Boisbriand, QC · 103,000 km	$35,995
Ste-Marie de Beauce, QC · 37,392 km	$54,900
Toronto, ON · 178,049 km	$46,999
Toronto, ON · 289,833 km	$28,999

§4 EVENTS

2021 Model year 2021[1]
Assembly plant Charleston, South Carolina, United States

13 Apr 2021	Transport Canada recall 2021221[2] Issued for the model year · Lights and instruments
4 Jun 2021	Transport Canada recall 2021349[2] Issued for the model year · Visual system
6 Aug 2021	Transport Canada recall 2021494[2] Issued for the model year · Seats and restraints
7 Oct 2021	Transport Canada recall 2021620[2] Issued for the model year · Electrical
16 Dec 2021	Transport Canada recall 2021765[2] Issued for the model year · Powertrain
10 Feb 2022	Transport Canada recall 2022061[2] Issued for the model year · Label
27 Apr 2022	Transport Canada recall 2022214[2] Issued for the model year · Visual system
21 Oct 2022	Transport Canada recall 2022602[2] Issued for the model year · Powertrain
24 Mar 2023	Transport Canada recall 2023167[2] Issued for the model year · Lights and instruments
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
21 Dec 2023	Transport Canada recall 2023689[2] Issued for the model year · Structure
30 Jul 2026	Listed for sale, Toronto, ON[5] Smart Cars Sales · asking $28,500
28 Oct 2026	Listing last updated[5] asking $28,500

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 12 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.