Register entry, as of 28 October 2026 Listed for sale Record ID 6147bc23894a

# 2023 Mercedes-Benz Sprinter 907 (VS30)

2.0 L, 4 cylinders · 4x2 · Cargo Van · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| W1Y | 4KCHY | X | P | P | 591619 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mercedes-Benz, Ag | Sprinter · 2.0 L | Computes | 2023 | Germany | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 2.0 L, 4 cylinders |
| Make | Mercedes-Benz | Fuel | Diesel |
| Model | Sprinter | Drive | 4x2 |
| Trim | 907 (VS30) | Maker | MERCEDES-BENZ, AG |
| Body | Cargo Van | Plant | Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/sprinter/2023

**3** recalls listed by Transport Canada for this model year

### Suspension

2024395 5 Jul 2024

Issue: On certain vehicle, the U-bolts that attach the rear axle to the suspension may not have been manufactured properly. As a result, the axle could slide on the leaf spring. This could cause poor handling and lead to a loss of control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the leaf spring U-bolts.

### Structure

2024233 19 Apr 2024

Issue: On certain vehicles, the reinforcements on the B-pillar(s) may not have been properly welded. As a result, the front seat belt height adjuster(s) could fail in a crash. Safety Risk: A seat belt that does not work properly could increase the risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, repair the B-pillar(s).

### Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $63,995[5], $9,000 over the median of $54,995[4].

| | |
|---|---|
| Lowest ask | $38,880 |
| Middle half | $44,495 – $62,998 |
| Median ask | $54,995 |
| This car | $63,995 |

Same model year · 31 live listings · as of 28 Oct 2026

### OTHER 2023 MERCEDES-BENZ SPRINTER LISTINGS [5]

| | |
|---|---|
| Halifax, NS · 119,562 km | $65,990 |
| Ste-Marie de Beauce, QC · 198 km | $59,800 |
| Toronto, ON · 49,334 km | $48,999 |
| Toronto, ON · 58,751 km | $46,999 |
| Toronto, ON · 281,941 km | $39,999 |
| Halifax, NS · 76,929 km | $57,990 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Germany |
| 23 Jun 2023 | Transport Canada recall 2023353[2]<br>Issued for the model year · Fuel system |
| 19 Apr 2024 | Transport Canada recall 2024233[2]<br>Issued for the model year · Structure |
| 5 Jul 2024 | Transport Canada recall 2024395[2]<br>Issued for the model year · Suspension |
| 25 Oct 2025 | Listed for sale, St. Catharines, ON[5]<br>Can-Am Vehicle Exchange · asking $63,995 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $63,995 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 31 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.