Register entry, as of 29 October 2026 Listed for sale Record ID bfbd8c1d65ca

2021 Mercedes-Benz Metris 447 (VS20)

2.0 L, 4 cylinders · 4x2 · Cargo Van · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

W1Y	V0CEY	0	M	3	846487
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz, Ag	Metris · 2.0 L	Computes	2021	Vitoria	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	Metris	Drive	4x2
Trim	447 (VS20)	Maker	MERCEDES-BENZ, AG
Body	Cargo Van	Plant	Vitoria, Spain

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/metris/2021

6 recalls listed by Transport Canada for this model year

Tires

2026167 2 Apr 2026

Issue: On certain vehicles, winter tires with the wrong load rating may have been installed. As a result, the tires may be overloaded. This could cause poor handling or a tire failure. Safety Risk: Poor handling or a tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the winter tires.

Visual system

2025374 11 Jul 2025

Issue: On certain vehicles, there could be a problem with the connection of the infotainment system. As a result, the rearview camera image may not display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to secure the connection of the infotainment system.

Fuel system

2023672 15 Dec 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall 2023-353. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Fuel system

2022103 7 Mar 2022

Issue: On certain vehicles, the connections on the fuel supply hose may not be properly attached. As a result, fuel could leak in the engine compartment. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to check the upper and lower connections on the fuel transition hose. The dealer will replace the clamps and the fuel hose, if required.

Seats and restraints

2021494 6 Aug 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Note: The vehicle's lower universal anchorage system (UAS) is not affected by this defect and may still be used to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $33,990[5], $1,000 over the median of $32,990[4].

Lowest ask	$19,990
Middle half	$31,990 – $33,990
Median ask	$32,990
This car	$33,990

Same model year · 5 live listings · as of 29 Oct 2026

OTHER 2021 MERCEDES-BENZ METRIS LISTINGS [5]

Woodbridge, ON · 204,650 km	$19,990
Newmarket, ON · 79,748 km	$32,990
Newmarket, ON · 83,673 km	$31,990

§4 EVENTS

2021	Model year 2021[1] Assembly plant Vitoria, Spain
6 Aug 2021	Transport Canada recall 2021494[2] Issued for the model year · Seats and restraints

7 Mar 2022	Transport Canada recall 2022103[2] Issued for the model year · Fuel system
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system
15 Dec 2023	Transport Canada recall 2023672[2] Issued for the model year · Fuel system
11 Jul 2025	Transport Canada recall 2025374[2] Issued for the model year · Visual system
2 Apr 2026	Transport Canada recall 2026167[2] Issued for the model year · Tires
24 Oct 2026	Listed for sale, Woodbridge, ON[5] Palmery Motors · asking $33,990
29 Oct 2026	Listing last updated[5] asking $33,990

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 5 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.