Register entry, as of 26 October 2026 Listed for sale Record ID 08174ec94d35

2022 Mercedes-Benz Sprinter 907 (VS30) - Passenger Van

3.0 L, 6 cylinders · 4x2 · Van · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

W1Z	4EFHY	4	N	P	460638
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz, Ag	Sprinter · 3.0 L	Computes	2022	Germany	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Diesel
Model	Sprinter	Drive	4x2
Trim	907 (VS30) - Passenger Van	Maker	MERCEDES-BENZ, AG
Body	Van	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/sprinter/2022

4 recalls listed by Transport Canada for this model year

Fuel system

2023353 23 Jun 2023

Issue: On certain vehicles, the fuel delivery module could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel delivery module.

Lights and instruments

2023167 24 Mar 2023

Issue: On certain vehicles, a software problem could cause the instrument cluster not to work. As a result, you may not be able to see certain information about the vehicle, including the speedometer, fuel gauge, indicator lamps, and warning messages. In addition, the warning sounds may not work. Safety Risk: Warnings and malfunction tell-tale information that does not display could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the instrument cluster software.

Electrical

2023077 17 Feb 2023

Issue: On certain vehicles equipped with front swivel-seats, the wiring harness under the seat may not be properly secured. As a result, the airbag wires could be damaged when the seat is moved. If this happens, the side airbag may not work properly in a crash. Note: If the wiring to the side airbag is damaged, the SRS light will stay on in the instrument cluster. Safety Risk: An airbag that does not work properly could increase the risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the routing of the seat wiring harness and attach it correctly.

Powertrain

2022602 21 Oct 2022

Issue: In certain conditions, the vehicle could roll-away after placing the transmission in the "P" (Park) position if the parking brake is not set. Note: You should always follow the parking procedure in the owner's manual, and set the parking brake each time that you park. Safety Risk: A parked vehicle that rolls away could create a risk of a crash or an injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the software of various control units.

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $49,900[5], $10,112 over the median of $39,788[4].



Lowest ask	$28,900
Middle half	$34,994 – $47,495
Median ask	$39,788
This car	$49,900

Same model year · 27 live listings · as of 26 Oct 2026

OTHER 2022 MERCEDES-BENZ SPRINTER LISTINGS [5]

Boisbriand, QC · 211,000 km	$37,995
Woodbridge, ON · 100,500 km	$34,990
Woodbridge, ON · 41,500 km	$43,990
North York, ON · 171,484 km	$29,985
North York, ON · 173,850 km	$29,985
North York, ON · 165,955 km	$30,485

§4 EVENTS

2022	Model year 2022[1] Assembly plant Germany
21 Oct 2022	Transport Canada recall 2022602[2] Issued for the model year · Powertrain
17 Feb 2023	Transport Canada recall 2023077[2] Issued for the model year · Electrical
24 Mar 2023	Transport Canada recall 2023167[2] Issued for the model year · Lights and instruments
23 Jun 2023	Transport Canada recall 2023353[2] Issued for the model year · Fuel system

26 Oct 2026 Listed for sale, London, ON[5]
Finch Nissan · asking $49,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 27 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.