Register entry, as of 27 October 2026 Listed for sale Record ID 292b39e09903

2022 Audi Q5 S Line quattro Premium

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WA1	4AAFY	2	N	2	130286
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Audi Ag	Q5 · 2.0 L	Computes	2022	San José Chiapa	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.0 L, 4 cylinders
Make	Audi	Fuel	Gasoline
Model	Q5	Drive	AWD
Trim	S Line quattro Premium	Maker	AUDI AG
Body	Sport Utility Vehicle	Plant	San José Chiapa, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/q5/2022

10 recalls listed by Transport Canada for this model year

High voltage

2025369 10 Jul 2025

Issue: On certain vehicles, the high-voltage battery could overheat. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Note: This recall only affects plug-in hybrid (PHEV) models. This recall replaces Transport Canada recall no. 2025-064. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: To reduce the safety risk, Audi advises not to charge your vehicle until the recall repairs have been completed. Audi will notify owners by mail and advise you to take your vehicle to a dealership to install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module.

Engine

2025244 7 May 2025

Issue: On certain vehicles, the screws for the cylinder head cover could loosen and cause an oil leak. Safety Risk: Oil that leaks onto hot components can create the risk of a fire. Corrective Actions: Audi will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace and tighten the cylinder head cover screws.

High voltage

2025064 12 Feb 2025

This recall was replaced by Transport Canada recall no. 2025-369. Issue: On certain vehicles, the high-voltage battery could overheat. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Note: This recall only affects plug-in hybrid (PHEV) models. This recall replaces Transport Canada recall no. 2024-723. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: To reduce the safety risk, Audi advises not to charge your vehicle until the recall repairs have been completed. Audi will notify owners by mail and advise you to take your vehicle to a dealership to install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module.

High voltage

2024723 27 Nov 2024

This recall was replaced by Transport Canada recall no. 2025-064. Issue: On certain vehicles, the high-voltage battery could overheat. As a result, the battery could create smoke or heat, which can melt or damage the battery and nearby parts. Note: This recall only affects plug-in hybrid (PHEV) models. Safety Risk: A battery that overheats can create a fire risk. Corrective Actions: To reduce the safety risk, Audi advises not to charge your vehicle until the recall repairs have been completed. Audi will notify owners by mail and advise you to take your vehicle to a dealership to install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem. If you see this warning, you should contact a dealership to arrange replacement of the affected high-voltage battery module.

Accessories

2023659 13 Dec 2023

Issue: Under certain conditions, the plug for the 220 V compact vehicle charging cable could become damaged by the house power outlet. As a result, the cable could overheat while charging. Note: This recall only affects electric and plug-in hybrid electric (PHEV) models. Safety Risk: Wiring that overheats could create a fire risk. Corrective Actions: Audi will notify owners by mail and advise you to take your vehicle to a dealership to replace the vehicle charging cable. For unsold vehicles, the dealer will remove the charging cable before they are delivered to consumers.

Engine

2022576 7 Oct 2022

Issue: On certain vehicles, the connecting rod bearings may become damaged. If this happens, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail and/or an oil leak could occur. Safety Risk: An engine failure can cause a sudden loss of power, which could increase the risk of a crash. An oil leak could create the risk of a vehicle fire. Corrective actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership for an engine inspection test. The engine will be replaced, if necessary.

4 more on the model-year record, cardog.app/tools/recalls/audi/q5/2022

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $31,450[5], $1,462 over the median of $29,988[4].

Lowest ask	$18,999
Middle half	$26,894 – $31,720
Median ask	$29,988
This car	$31,450

Same model year · 51 live listings · as of 27 Oct 2026

OTHER 2022 AUDI Q5 LISTINGS [5]

Edmonton, AB · 119,448 km	$31,020
Smiths Falls, ON · 88,458 km	$31,995
Burlington, ON · 78,769 km	$29,988
North Vancouver, BC · 97,764 km	$36,995
Sherwood Park, AB · 98,531 km	$26,907
Edmonton, AB · 123,771 km	$26,997

§4 EVENTS

2022	Model year 2022[1] Assembly plant San José Chiapa, Mexico
20 Oct 2021	Transport Canada recall 2021642[2] Issued for the model year · Visual system
9 Dec 2021	Transport Canada recall 2021740[2] Issued for the model year · Electrical
23 May 2022	Transport Canada recall 2022266[2] Issued for the model year · Engine
3 Aug 2022	Transport Canada recall 2022455[2] Issued for the model year · Structure
7 Oct 2022	Transport Canada recall 2022576[2] Issued for the model year · Engine
13 Dec 2023	Transport Canada recall 2023659[2] Issued for the model year · Accessories
27 Nov 2024	Transport Canada recall 2024723[2] Issued for the model year · High voltage
12 Feb 2025	Transport Canada recall 2025064[2] Issued for the model year · High voltage
7 May 2025	Transport Canada recall 2025244[2] Issued for the model year · Engine
10 Jul 2025	Transport Canada recall 2025369[2] Issued for the model year · High voltage
25 Oct 2026	Listed for sale, Toronto, ON[5] Autorama · asking $31,450
27 Oct 2026	Listing last updated[5] asking $31,450

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 51 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.