

Register entry, as of 28 October 2026

Listed for sale

Record ID 77dc3ff29ae3

2022 Audi SQ5 quattro Premium

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**WA1 A4AFY 7 N 2 068247**

WMI 1-3

Audi Ag

DESCRIPTOR 4-8

SQ5 · 3.0 L

CHECK 9

Computes

YEAR 10

2022

PLANT 11

San José Chiapa

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2022	Engine	3.0 L, 6 cylinders
Make	Audi	Fuel	Gasoline
Model	SQ5	Drive	AWD
Trim	quattro Premium	Maker	AUDI AG
Body	Sport Utility Vehicle	Plant	San José Chiapa, Mexico

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/audi/sq5/2022

2 recalls listed by Transport Canada for this model year

Structure

2022455 3 Aug 2022

Issue: On a small number of Q5 Sportback and SQ5 Sportback models, the rear hatch lid may not have been manufactured correctly. As a result, the latch could break or detach in a crash and allow the rear hatch to deform more than it is designed to. Safety Risk: A rear hatch that deforms too much during a crash could lead to an increased risk of injury. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealership to replace the rear hatch lid.

Electrical

2021740 9 Dec 2021

Issue: On certain vehicles, if you spill liquid on the rear seat, or drive through heavy rain or deep water, the gateway control module could be damaged. If this happens, the vehicle may enter emergency mode and suddenly lose power to the wheels. Note: The power steering and braking systems will continue to work. You may also see warning messages on the instrument panel when this happens. Safety Risk: A sudden loss of power to the wheels may increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to install a protective cover on the gateway control module and seal an underbody seam, as necessary.

Listed for the model year, not checked against your VIN. Audi confirms which apply.

Check your VIN with Audi Canada or call a Audi dealer with your VIN.


www.audi.ca/en/recalls/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]



§3 VALUE [4]

This car asks \$38,795^[5], \$863 under the median of \$39,658^[4].



Lowest ask	\$35,790
Middle half	\$37,733 – \$42,925
Median ask	\$39,658
This car	\$38,795

Same model year · 16 live listings · as of 28 Oct 2026

OTHER 2022 AUDI SQ5 LISTINGS [5]

Airdrie, AB · 117,549 km	\$36,887
Calgary, AB · 117,549 km	\$36,887
Calgary, AB · 117,549 km	\$36,887
Strathmore, AB · 117,549 km	\$36,887
Vancouver, BC · 45,952 km	\$44,995
North Vancouver, BC · 45,952 km	\$44,995

§4 EVENTS

2022	Model year 2022 ^[1] Assembly plant San José Chiapa, Mexico
9 Dec 2021	Transport Canada recall 2021740 ^[2] Issued for the model year · Electrical
3 Aug 2022	Transport Canada recall 2022455 ^[2] Issued for the model year · Structure
4 Aug 2026	Listed for sale, Brossard, QC ^[5] Park Avenue Honda · asking \$38,795
27 Oct 2026	Listing last updated ^[5] asking \$38,795

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same model year, 16 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

