Register entry, as of 29 October 2026 Listed for sale Record ID e6f022fed17e

2021 Audi SQ5 quattro Prestige

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WA1	C4AFY	6	M	2	045887
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Audi Ag	SQ5 · 3.0 L	Computes	2021	San José Chiapa	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.0 L, 6 cylinders
Make	Audi	Fuel	Gasoline
Model	SQ5	Drive	AWD
Trim	quattro Prestige	Maker	AUDI AG
Body	Sport Utility Vehicle	Plant	San José Chiapa, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/sq5/2021

5 recalls listed by Transport Canada for this model year

Visual system

2022565 5 Oct 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to update the infotainment software.

Suspension

2022022 26 Jan 2022

Issue: On certain vehicles, the rear wheel alignment was not checked during recall 42L1 (Transport Canada Recall 2021-249). As a result, the steering could pull to one side or another and the tires could wear unevenly. If you continue to drive the vehicle in this condition, there may be reduced traction. Eventually, a tire could fail and lose air pressure. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect and adjust the rear wheel alignment, as necessary. Additionally, the dealer will inspect the rear tires for premature and uneven wear due to this issue, and replace them if necessary.

Electrical

2021740 9 Dec 2021

Issue: On certain vehicles, if you spill liquid on the rear seat, or drive through heavy rain or deep water, the gateway control module could be damaged. If this happens, the vehicle may enter emergency mode and suddenly lose power to the wheels. Note: The power steering and braking systems will continue to work. You may also see warning messages on the instrument panel when this happens. Safety Risk: A sudden loss of power to the wheels may increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to install a protective cover on the gateway control module and seal an underbody seam, as necessary.

Seats and restraints

2021486 4 Aug 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

Suspension

2021249 26 Apr 2021

Issue: On certain vehicles, the lock nuts for the rear trailing arm bolts may be defective. If a nut breaks, there could be sudden changes in rear wheel alignment. This can cause a loss of vehicle stability. Safety Risk: Reduced vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear trailing arm lock nuts. If necessary, the associated bolt(s) will be replaced as well.

Listed for the model year, not checked against your VIN. Audi confirms which apply.
Check your VIN with Audi Canada or call a Audi dealer with your VIN.
www.audi.ca/en/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $37,499[5], $1,605 over the median of $35,894[4].



Lowest ask	$28,950
Middle half	$33,170 – $37,058
Median ask	$35,894
This car	$37,499

Same model year · 18 live listings · as of 29 Oct 2026

OTHER 2021 AUDI SQ5 LISTINGS [5]

Bomanville, ON · 123,125 km	$30,935
Laval, QC · 137,584 km	$29,590
North York, ON · 108,000 km	$33,999
Cochrane, AB · 90,018 km	$35,888
Port Coquitlam, BC · 111,415 km	$33,995
Dartmouth, NS · 78,849 km	$37,082

§4 EVENTS

2021	Model year 2021[1] Assembly plant San José Chiapa, Mexico
26 Apr 2021	Transport Canada recall 2021249[2] Issued for the model year · Suspension
4 Aug 2021	Transport Canada recall 2021486[2] Issued for the model year · Seats and restraints

9 Dec 2021	Transport Canada recall 2021740[2] Issued for the model year · Electrical
26 Jan 2022	Transport Canada recall 2022022[2] Issued for the model year · Suspension
5 Oct 2022	Transport Canada recall 2022565[2] Issued for the model year · Visual system
19 Jul 2026	Listed for sale, Oakville, ON[5] Oakville Chrysler Dodge Jeep Ram Ltd. · asking $37,499
29 Oct 2026	Listing last updated[5] asking $37,499

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 18 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.