Register entry, as of 28 October 2026 Listed for sale Record ID de7defe8a957

2022 Audi Q3 S Line quattro Premium Plus

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WA1	EECF3	0	N	1	041041
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Audi Ag	Q3 · 2.0 L	Computes	2022	Gyor	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.0 L, 4 cylinders
Make	Audi	Fuel	Gasoline
Model	Q3	Drive	AWD
Trim	S Line quattro Premium Plus	Maker	AUDI AG
Body	Sport Utility Vehicle	Plant	Gyor, Hungary

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/q3/2022

5 recalls listed by Transport Canada for this model year

Visual system

2022611 26 Oct 2022

Issue: On certain vehicles, the infotainment main unit in the center console could fail. If this happens, the display screen will not turn on when you start the vehicle and the rearview camera image will not appear when backing up. Canadian regulations require the rearview image to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealership to replace the infotainment unit.

Fuel system

2022503 8 Sep 2022

Issue: On certain vehicles, the vent pipe inside the fuel tank may be damaged. As a result, gasoline could spill out of the filler neck when you remove the fuel cap. Safety Risk: A fuel spill could create the risk of injury or a fire. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the fuel tank vent pipe. If fuel spills out of the filler neck when the tank is pressurized, the dealer will replace the fuel tank and charcoal canister.

Wheels

2022385 21 Jul 2022

Issue: On certain vehicles, the rim size marking on the wheels may be unreadable. Canadian regulations require wheels to be clearly marked with the rim size. Safety Risk: This small error does not affect safety. The rim size information can be found on the compliance label. Corrective Actions: This is not a recall. Audi has made changes to ensure that all new wheels are marked correctly.

Visual system

2022054 7 Feb 2022

Issue: On certain vehicles, the software update for recall 91CR (Transport Canada Recall 2021-642) may not have been performed correctly. As a result, a second repair is required. Under certain conditions, a software problem could cause a delay before the rearview camera image appears. Canadian regulations require the rearview image to display within 2 seconds of shifting the transmission into reverse gear. Safety Risk: A rearview camera that is slow to turn on could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to update the vehicle infotainment unit parameters.

Visual system

2021642 20 Oct 2021

Issue: Under certain conditions, a software problem could cause a delay before the rearview camera image appears. Canadian regulations require the rearview image to display within 2 seconds of shifting the transmission into reverse gear. Safety Risk: A rearview camera that is slow to turn on could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to update the vehicle infotainment unit parameters.

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $34,995[5], $5,795 over the median of $29,200[4].

Lowest ask	$24,950
Middle half	$28,499 – $32,488
Median ask	$29,200
This car	$34,995

Same configuration · 13 live listings · as of 28 Oct 2026

OTHER 2022 AUDI Q3 LISTINGS [5]

Calgary, AB · 78,385 km	$19,700
Concord, ON · 54,538 km	$27,800
Laval, QC · 90,963 km	$22,995
Toronto, ON · 76,728 km	$26,900
Nanaimo, BC · 113,333 km	$27,977
St-Eustache, QC · 89,932 km	$23,497

§4 EVENTS

2022	Model year 2022[1] Assembly plant Gyor, Hungary
20 Oct 2021	Transport Canada recall 2021642[2] Issued for the model year · Visual system
7 Feb 2022	Transport Canada recall 2022054[2] Issued for the model year · Visual system

21 Jul 2022	Transport Canada recall 2022385[2] Issued for the model year · Wheels
8 Sep 2022	Transport Canada recall 2022503[2] Issued for the model year · Fuel system
26 Oct 2022	Transport Canada recall 2022611[2] Issued for the model year · Visual system
26 Oct 2026	Listed for sale, Orangeville, ON[5] Orangeville Autosport · asking $34,995
27 Oct 2026	Listing last updated[5] asking $34,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 13 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.