Register entry, as of 27 October 2026 Listed for sale Record ID 5c81a0d9afa1

2019 Audi Q5

2.0 L, 4 cylinders · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WA1	ENAFY	8	K	2	137148
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Audi Ag	Q5 · 2.0 L	Computes	2019	San Jose Chiapa	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	2.0 L, 4 cylinders
Make	Audi	Fuel	Gasoline
Model	Q5	Drive	Not in the decode
Trim	Not in the decode	Maker	AUDI AG
Body	Not in the decode	Plant	San Jose Chiapa, Chiapas, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/q5/2019

5 recalls listed by Transport Canada for this model year

Electrical

2021740 9 Dec 2021

Issue: On certain vehicles, if you spill liquid on the rear seat, or drive through heavy rain or deep water, the gateway control module could be damaged. If this happens, the vehicle may enter emergency mode and suddenly lose power to the wheels. Note: The power steering and braking systems will continue to work. You may also see warning messages on the instrument panel when this happens. Safety Risk: A sudden loss of power to the wheels may increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to install a protective cover on the gateway control module and seal an underbody seam, as necessary.

Structure

2019520 16 Oct 2019

Issue: On certain vehicles, the cover trim for the rear wheel arches may become loose. This could cause the trim to detach while driving. Safety Risk: Trim that completely detaches from the vehicle could create a road hazard for others. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to replace the four clips that secure the forward part of the rear wheel arch trims.

Airbag

2019307 19 Jun 2019

Issue: In a crash where the passenger-front airbag deploys, the instrument panel structure may break. This could cause damage to the airbag and cause it not to inflate properly. Safety Risk: An airbag that does not work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to replace the instrument panel and the passenger-front airbag.

Structure

2019265 5 Jun 2019

Issue: On certain vehicles, the cover trim for the wheel arches may become loose. This could cause the trim to detach while driving. Safety Risk: Trim that completely detaches from the vehicle could create a road hazard for others. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to secure each wheel arch trim with an additional screw and nut.

Brakes

2019173 8 Apr 2019

Issue: Some vehicles were built with an incorrect brake master cylinder. The master cylinder may be too short, which could cause it to fail. This could cause a complete loss of braking (with the exception of the emergency/parking brake function). Safety Risk: A loss of brakes can create the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the brake master cylinder. If your vehicle is equipped with the incorrect part, it will be replaced with the correct one.

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $19,490[5], the median[4].

Lowest ask	$10,989
Middle half	$16,492 – $22,942
Median ask	$19,490
This car	$19,490

Same configuration · 11 live listings · as of 27 Oct 2026

OTHER 2019 AUDI Q5 LISTINGS [5]

Welland, ON · 139,839 km	$17,995
Hamilton, ON · 145,645 km	$17,400
Amherst, NS · 165,462 km	$16,975
Sherwood Park, AB · 195,404 km	$14,980
Sherwood Park, AB · 195,404 km	$14,980
Longueuil, QC · 100,400 km	$17,990

§4 EVENTS

2019	Model year 2019[1] Assembly plant San Jose Chiapa, Chiapas, Mexico
8 Apr 2019	Transport Canada recall 2019173[2] Issued for the model year · Brakes
5 Jun 2019	Transport Canada recall 2019265[2] Issued for the model year · Structure
19 Jun 2019	Transport Canada recall 2019307[2] Issued for the model year · Airbag

16 Oct 2019	Transport Canada recall 2019520[2] Issued for the model year · Structure
9 Dec 2021	Transport Canada recall 2021740[2] Issued for the model year · Electrical
26 Oct 2026	Listed for sale, Dorval, QC[5] autosetfreres.com · asking $19,490
27 Oct 2026	Listing last updated[5] asking $19,490

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 11 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.