Register entry, as of 29 October 2026 Listed for sale Record ID de75e81636d9

# 2021 Audi Q8 S Line quattro Prestige

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WA1 | FVAF1 | 9 | M | D | 029586 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Audi Ag | Q8 · 3.0 L | Computes | 2021 | Bratislava | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 3.0 L, 6 cylinders |
| Make | Audi | Fuel | Gasoline |
| Model | Q8 | Drive | AWD |
| Trim | S Line quattro Prestige | Maker | AUDI AG |
| Body | Sport Utility Vehicle | Plant | Bratislava, Slovakia |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/q8/2021

**7** recalls listed by Transport Canada for this model year

### Visual system

2025713 19 Dec 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and advise you to take your vehicle to a dealership to update the rearview camera software.

### Lights and instruments

2025167 31 Mar 2025

Issue: On certain vehicles, a problem with the instrument cluster (virtual cockpit) could cause it to shut down. If this happens, you may not be able to see certain information about the vehicle, including the speedometer, warnings, and tell-tales. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and advise you to take your vehicle to a dealership to update the instrument cluster software.

### Visual system

2022565 5 Oct 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to update the infotainment software.

### Fuel system

2022384 20 Jul 2022

Issue: On certain vehicles, the fuel delivery module inside the fuel tank could fail. If this happens, the engine may run rough or may not start. This could also result in a sudden loss of engine power while driving. Note: This problem could cause the emission control system warning light to turn on. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Audi will contact owners by mail and instruct you to bring your vehicle to a dealership to replace the fuel delivery module.

### Suspension

2022022 26 Jan 2022

Issue: On certain vehicles, the rear wheel alignment was not checked during recall 42L1 (Transport Canada Recall 2021-249). As a result, the steering could pull to one side or another and the tires could wear unevenly. If you continue to drive the vehicle in this condition, there may be reduced traction. Eventually, a tire could fail and lose air pressure. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect and adjust the rear wheel alignment, as necessary. Additionally, the dealer will inspect the rear tires for premature and uneven wear due to this issue, and replace them if necessary.

### Seats and restraints

2021486 4 Aug 2021

Issue: On certain vehicles, the passenger seat belt assemblies may contain defective automatic locking retractors (ALR). As a result, the seat belts may not properly lock to secure a child seat. Safety Risk: A seat belt that is used to secure a child restraint but is not properly locked could increase the risk of injury in a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the seat belts. They will be replaced, if necessary.

1 more on the model-year record, cardog.app/tools/recalls/audi/q8/2021

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $42,888[5], $941 under the median of $43,829[4].

| | |
|---|---|
| Lowest ask | $35,888 |
| Middle half | $37,741 – $44,924 |
| Median ask | $43,829 |
| This car | $42,888 |

Same model year · 8 live listings · as of 29 Oct 2026

### OTHER 2021 AUDI Q8 LISTINGS [5]

| | |
|---|---|
| Waterloo, ON · 104,063 km | $36,995 |
| Trois-Rivières, QC · 88,126 km | $44,995 |
| Vaughan, ON · 80,600 km | $44,900 |
| Oakville, ON · 92,880 km | $45,496 |
| Port Coquitlam, BC · 118,179 km | $35,888 |
| Toronto, ON · 67,000 km | $44,770 |

## §4 EVENTS

| | |
|---|---|
| 2021 | Model year 2021[1]<br>Assembly plant Bratislava, Slovakia |
| 26 Apr 2021 | Transport Canada recall 2021249[2]<br>Issued for the model year · Suspension |
| 4 Aug 2021 | Transport Canada recall 2021486[2]<br>Issued for the model year · Seats and restraints |
| 26 Jan 2022 | Transport Canada recall 2022022[2]<br>Issued for the model year · Suspension |
| 20 Jul 2022 | Transport Canada recall 2022384[2]<br>Issued for the model year · Fuel system |
| 5 Oct 2022 | Transport Canada recall 2022565[2]<br>Issued for the model year · Visual system |
| 31 Mar 2025 | Transport Canada recall 2025167[2]<br>Issued for the model year · Lights and instruments |
| 19 Dec 2025 | Transport Canada recall 2025713[2]<br>Issued for the model year · Visual system |
| 20 Oct 2026 | Listed for sale, Mississauga, ON[5]<br>B Town Auto Sales · asking $42,888 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $42,888 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 8 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.