Register entry, as of 28 October 2026 Listed for sale Record ID f3c1f32181da

# 2017 Audi Q7 quattro Prestige

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WA1 | VAAF7 | 6 | H | D | 016232 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Audi Ag | Q7 · 3.0 L | Computes | 2017 | Bratislava | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2017 | Engine | 3.0 L, 6 cylinders |
| Make | Audi | Fuel | Gasoline |
| Model | Q7 | Drive | AWD |
| Trim | quattro Prestige | Maker | AUDI AG |
| Body | Sport Utility Vehicle | Plant | Bratislava, Slovakia |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/q7/2017

**6** recalls listed by Transport Canada for this model year

### Steering

2020102 16 Mar 2020

Issue: On certain vehicles, the bolt that attaches the steering shaft to the steering gear may not be properly tightened. Over time, the bolt may loosen. If you continue to operate the vehicle, the bolt could detach completely and cause a loss of steering control. Safety Risk: A loss of steering could create the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the steering shaft bolt and, if necessary, replace it.

### Fuel system

2019024 17 Jan 2019

Issue: On certain vehicles, a small amount of fuel may leak from one or both fuel rails. Safety Risk: Leaking fuel in the presence of an ignition source could increase the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the left and right fuel rails replaced.

### Airbag

2016662 30 Dec 2016

Certain vehicles may have been equipped with airbag and/or pretensioner igniters that do not meet specifications. This could cause affected airbags and/or pretentioners to fail to deploy properly in the event of a crash, which could increase the risk of injury to vehicle occupants. Correction: Dealers will replace affected airbag and/or pretentioner.

### Lights and instruments

2016427 2 Sep 2016

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 108 - Lighting System and Retroreflective Devices. In a situation where the parking lights are switched on and the vehicle is locked, the side marker lights do not illuminate, which is contrary to the requirements of the standard. This could reduce vehicle visibility, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update vehicle software.

### Seats and restraints

2016426 2 Sep 2016

Certain vehicles may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 207 - Anchorage of Seats. The third row seat may move forward if subject to high loading, such as in a frontal collision. As a result, it may not adequately restrain an occupant and would increase the risk of injury, and cause it to not conform to the standard. Correction: Dealers will install an additional support bracket.

### Airbag

2016348 6 Jul 2016

On certain vehicles, the software of the airbag control module may be incorrect. This could cause the frontal airbags to deploy (where deployment is warranted) with too much force in relation to the type of crash, which could increase the risk of injury to vehicle occupants. Correction: Dealers will update the airbag control module software.

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $17,888[5], $2,057 under the median of $19,945[4].




| | |
|---|---|
| Lowest ask | $12,995 |
| Middle half | $16,866 – $23,497 |
| Median ask | $19,945 |
| This car | $17,888 |

Same model year · 32 live listings · as of 28 Oct 2026

OTHER 2017 AUDI Q7 LISTINGS [5]

| | |
|---|---|
| Calgary, AB · 175,185 km | $14,998 |
| Vaudreuil-Dorion, QC · 147,075 km | $17,991 |
| Montréal, QC · 116,377 km | $20,995 |
| Saint-Laurent, QC · 115,609 km | $19,895 |
| Gloucester, ON · 175,000 km | $16,990 |
| Montréal, QC · 146,000 km | $14,995 |

## §4 EVENTS

| | |
|---|---|
| 2017 | Model year 2017[1]<br>Assembly plant Bratislava, Slovakia |
| 6 Jul 2016 | Transport Canada recall 2016348[2]<br>Issued for the model year · Airbag |
| 2 Sep 2016 | Transport Canada recall 2016427[2]<br>Issued for the model year · Lights and instruments |
| 2 Sep 2016 | Transport Canada recall 2016426[2]<br>Issued for the model year · Seats and restraints |

| | |
|---|---|
| 30 Dec 2016 | Transport Canada recall 2016662[2]<br>Issued for the model year · Airbag |
| 17 Jan 2019 | Transport Canada recall 2019024[2]<br>Issued for the model year · Fuel system |
| 16 Mar 2020 | Transport Canada recall 2020102[2]<br>Issued for the model year · Steering |
| 22 Apr 2026 | Listed for sale, Scarborough, ON[5]<br>Kingscross Hyundai · asking $17,888 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $17,888 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 32 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.