Register entry, as of 28 October 2026 Listed for sale Record ID b659dd40bdf9

2014 Audi A8

3.0 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WAU	AGAFD	3	E	N	007578
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Audi Ag	A8 · 3.0 L	Computes	2014	Neckarsulm	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.0 L, 6 cylinders
Make	Audi	Fuel	Gasoline
Model	A8	Drive	Not in the decode
Trim	Not in the decode	Maker	AUDI AG
Body	Sedan	Plant	Neckarsulm, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/a8/2014

5 recalls listed by Transport Canada for this model year

Engine

2022133 23 Mar 2022

Issue: On certain vehicles, the oil strainer for the turbocharger oil supply could get blocked. If this happens, a turbocharger could fail. This could cause loss of engine power and/or cause the engine to stall. Note: This problem could cause different warning messages to display or the engine oil warning light to turn on. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealership to replace the oil strainer for the turbocharger oil supply. The dealer will also inspect and document the performance of the boost pressure system and change the engine oil.

Structure

2020308 7 Jul 2020

Issue: On certain vehicles, the engine compartment seal may become loose over time and fall into the engine compartment. If this happens, the seal could contact a hot surface in the engine compartment. Safety Risk: A rubber seal that falls onto a hot surface could cause a fire. Corrective Action: The company will notify owners by mail and instruct you to take your vehicle to a dealer to install a retaining plate on the engine compartment seal.

Fuel system

2019040 28 Jan 2019

Issue: On certain vehicles, the fuel line to the high-pressure fuel pump could leak. This may cause a gasoline odour or leak. Safety Risk: Leaking fuel, in the presence of an ignition source, creates the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for repair. A fuel pressure damper will be installed in the low pressure fuel supply located inside the fuel tank.

Fuel system

2018344 26 Jun 2018

On certain vehicles, the fuel supply line for the high pressure fuel pump may become porous over time. This could cause a fuel smell or a fuel leak, which in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will replace the fuel line.

Accessories

2013321 23 Sep 2013

On certain vehicle the sunroof may have been manufactured incorrectly and could be susceptible to breakage. Sunroof glass panel breakage, while the vehicle is in motion, could cause driver distraction, which could result in a crash causing property damage and/or personal injury. Additionally, broken glass inside the vehicle could pose a risk of injury to vehicle occupants. Correction: Dealers will replace the sunroof glass panel.

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $18,995[5], $5,453 under the median of $24,448[4].

Lowest ask	$18,995
Middle half	$21,721 – $27,174
Median ask	$24,448
This car	$18,995

Same model year · 2 live listings · as of 28 Oct 2026

OTHER 2014 AUDI A8 LISTINGS [5]

North York, ON · 119,864 km	$29,900

§4 EVENTS

2014	Model year 2014[1] Assembly plant Neckarsulm, Germany
23 Sep 2013	Transport Canada recall 2013321[2] Issued for the model year · Accessories
26 Jun 2018	Transport Canada recall 2018344[2] Issued for the model year · Fuel system
28 Jan 2019	Transport Canada recall 2019040[2] Issued for the model year · Fuel system
7 Jul 2020	Transport Canada recall 2020308[2] Issued for the model year · Structure
23 Mar 2022	Transport Canada recall 2022133[2] Issued for the model year · Engine

24 Nov 2025	Listed for sale, Toronto, ON[5] 11 MOTORS · asking $18,995
25 Oct 2026	Listing last updated[5] asking $18,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 2 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.