Register entry, as of 28 October 2026 Listed for sale Record ID 19c846c53b82

2017 Audi A4 quattro Premium

2.0 L, 4 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WAU	ANAF4	0	H	N	068414
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Audi Ag	A4 · 2.0 L	Computes	2017	Neckarsulm	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	2.0 L, 4 cylinders
Make	Audi	Fuel	Gasoline
Model	A4	Drive	AWD
Trim	quattro Premium	Maker	AUDI AG
Body	Sedan	Plant	Neckarsulm, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/a4/2017

5 recalls listed by Transport Canada for this model year

Airbag

2021688 10 Nov 2021

Issue: On certain vehicles, the passenger occupant detection system (PODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Additional note: For the 2020 model year A5 model, only the A5 Sportback is affected by this recall. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Audi will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the front passenger seat. Depending on the seat type, the dealer will either replace the seat heating mat including the connecting cable or the entire seat cover.

Airbag

2019361 24 Jul 2019

Issue: On certain vehicles, the passenger occupant detection system (PODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to install cable ties on the wiring harness under the front passenger seat.

Other

2017520 26 Oct 2017

On certain vehicles, the aluminum trim on the front and rear door speaker covers could come loose. If this were to occur, the loosened trim may bend away from the speaker cover and could expose sharp edges, which could increase the risk of injury to occupants. Correction: Dealers will remove the aluminum trim from the speaker covers and replace the trim with an updated part. Note: For the A5 model, it is only the A5 Sportback that is involved in this campaign.

Airbag

2016662 30 Dec 2016

Certain vehicles may have been equipped with airbag and/or pretensioner igniters that do not meet specifications. This could cause affected airbags and/or pretentioners to fail to deploy properly in the event of a crash, which could increase the risk of injury to vehicle occupants. Correction: Dealers will replace affected airbag and/or pretentioner.

Lights and instruments

2016427 2 Sep 2016

Certain vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 108 - Lighting System and Retroreflective Devices. In a situation where the parking lights are switched on and the vehicle is locked, the side marker lights do not illuminate, which is contrary to the requirements of the standard. This could reduce vehicle visibility, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will update vehicle software.

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 1 NHTSA record for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $11,995[5], $2,504 under the median of $14,499[4].



Lowest ask	$8,989
Middle half	$12,966 – $15,993
Median ask	$14,499
This car	$11,995

Same configuration · 16 live listings · as of 28 Oct 2026

OTHER 2017 AUDI A4 LISTINGS [5]

Château-Richer, QC · 138,000 km	$12,995
Québec, QC · 174,899 km	$14,950
Saint-Sulpice, QC · 97,653 km	$15,995
Château-Richer, QC · 157,000 km	$12,495
Montréal, QC · 167,000 km	$14,395
Québec, QC · 174,413 km	$14,493

§4 EVENTS

2017	Model year 2017[1] Assembly plant Neckarsulm, Germany
2 Sep 2016	Transport Canada recall 2016427[2] Issued for the model year · Lights and instruments
30 Dec 2016	Transport Canada recall 2016662[2] Issued for the model year · Airbag
26 Oct 2017	Transport Canada recall 2017520[2] Issued for the model year · Other

24 Jul 2019	Transport Canada recall 2019361[2] Issued for the model year · Airbag
10 Nov 2021	Transport Canada recall 2021688[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Montréal, QC[5] groupeautoflex.ca · asking $11,995
27 Oct 2026	Listing last updated[5] asking $11,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 16 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.