

Register entry, as of 27 October 2026

Listed for sale

Record ID a86ab241be22

2020 Audi S4

2.0 L, 4 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**WAU ANAF4 8 L N 010883**WMI 1-3
Audi AgDESCRIPTOR 4-8
S4 · 2.0 LCHECK 9
ComputesYEAR 10
2020PLANT 11
NeckarsulmSERIAL 12-17
Build sequence

§1 IDENTITY ^[1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Audi	Fuel	Gasoline
Model	S4	Drive	AWD
Trim	Not in the decode	Maker	AUDI AG
Body	Sedan	Plant	Neckarsulm, Germany

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/audi/s4/2020

2 recalls listed by Transport Canada for this model year

Suspension

2022022 26 Jan 2022

Issue: On certain vehicles, the rear wheel alignment was not checked during recall 42L1 (Transport Canada Recall 2021-249). As a result, the steering could pull to one side or another and the tires could wear unevenly. If you continue to drive the vehicle in this condition, there may be reduced traction. Eventually, a tire could fail and lose air pressure. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect and adjust the rear wheel alignment, as necessary. Additionally, the dealer will inspect the rear tires for premature and uneven wear due to this issue, and replace them if necessary.

Suspension

2021249 26 Apr 2021


Issue: On certain vehicles, the lock nuts for the rear trailing arm bolts may be defective. If a nut breaks, there could be sudden changes in rear wheel alignment. This can cause a loss of vehicle stability. Safety Risk: Reduced vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear trailing arm lock nuts. If necessary, the associated bolt(s) will be replaced as well.

Listed for the model year, not checked against your VIN. Audi confirms which apply.
Check your VIN with Audi Canada or call a Audi dealer with your VIN.
www.audi.ca/en/recalls/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$24,394^[5], \$3,943 under the median of \$28,337^[4].



Lowest ask	\$20,999
Middle half	\$23,000 – \$29,999
Median ask	\$28,337
This car	\$24,394

Same model year · 9 live listings · as of 27 Oct 2026

OTHER 2020 AUDI S4 LISTINGS [5]

Scarborough, ON · 77,074 km	\$37,990
North York, ON · 145,327 km	\$28,995
Oakville, ON · 79,804 km	\$40,388

§4 EVENTS

2020	Model year 2020 ^[1] Assembly plant Neckarsulm, Germany
26 Apr 2021	Transport Canada recall 2021249 ^[2] Issued for the model year · Suspension
26 Jan 2022	Transport Canada recall 2022022 ^[2] Issued for the model year · Suspension
26 Oct 2026	Listed for sale, St-Eustache, QC ^[5] Hamel Honda · asking \$24,394
27 Oct 2026	Listing last updated ^[5] asking \$24,394

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 9 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

