

Register entry, as of 29 October 2026

Listed for sale

Record ID dc9aec9191fc

2020 Audi S5 quattro Premium Plus

3.0 L, 6 cylinders · AWD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WAU B4CF5 1 L A 006628

WMI 1-3

Audi Ag

DESCRIPTOR 4-8

S5 · 3.0 L

CHECK 9

Computes

YEAR 10

2020

PLANT 11

Ingolstadt

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	3.0 L, 6 cylinders
Make	Audi	Fuel	Gasoline
Model	S5	Drive	AWD
Trim	quattro Premium Plus	Maker	AUDI AG
Body	Hatchback	Plant	Ingolstadt, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/s5/2020

4 recalls listed by Transport Canada for this model year

Suspension

2022022 26 Jan 2022

Issue: On certain vehicles, the rear wheel alignment was not checked during recall 42L1 (Transport Canada Recall 2021-249). As a result, the steering could pull to one side or another and the tires could wear unevenly. If you continue to drive the vehicle in this condition, there may be reduced traction. Eventually, a tire could fail and lose air pressure. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to inspect and adjust the rear wheel alignment, as necessary. Additionally, the dealer will inspect the rear tires for premature and uneven wear due to this issue, and replace them if necessary.

Airbag

2021688 10 Nov 2021

Issue: On certain vehicles, the passenger occupant detection system (PODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Additional note: For the 2020 model year A5 model, only the A5 Sportback is affected by this recall. Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Audi will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the front passenger seat. Depending on the seat type, the dealer will either replace the seat heating mat including the connecting cable or the entire seat cover.

Suspension

2021249 26 Apr 2021

Issue: On certain vehicles, the lock nuts for the rear trailing arm bolts may be defective. If a nut breaks, there could be sudden changes in rear wheel alignment. This can cause a loss of vehicle stability. Safety Risk: Reduced vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to replace the rear trailing arm lock nuts. If necessary, the associated bolt(s) will be replaced as well.



Electrical

2020575 25 Nov 2020

Issue: On certain vehicles, a layer of protective tape may not have been installed around a wiring harness in the spare tire area. As a result, the wiring harness could become damaged in a rear crash. If this happens, it may not be possible to open the doors from the outside and/or the hazard lights may not work. Safety Risk: Doors that cannot be opened from the outside could increase the risk of injury after a crash. Hazard lights that do not work could make the vehicle less visible and increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealer to apply protective tape to the wiring harness for the rear lights.

Listed for the model year, not checked against your VIN. Audi confirms which apply.


Check your VIN with Audi Canada or call a Audi dealer with your VIN.

www.audi.ca/en/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$33,789^[5], \$704 under the median of \$34,493^[4].



Lowest ask	\$25,888
Middle half	\$32,916 – \$44,190
Median ask	\$34,493
This car	\$33,789

Same model year · 8 live listings · as of 29 Oct 2026

OTHER 2020 AUDI S5 LISTINGS [5]

Burlington, ON · 53,112 km	\$43,990
Sudbury, ON · 111,350 km	\$34,991
Oakville, ON · 193,776 km	\$25,888
North York, ON · 125,419 km	\$29,995
Toronto, ON · 38,142 km	\$45,888
Aurora, ON · 38,142 km	\$45,888

§4 EVENTS

2020	Model year 2020 ^[1] Assembly plant Ingolstadt, Germany
25 Nov 2020	Transport Canada recall 2020575 ^[2] Issued for the model year · Electrical
26 Apr 2021	Transport Canada recall 2021249 ^[2] Issued for the model year · Suspension
10 Nov 2021	Transport Canada recall 2021688 ^[2] Issued for the model year · Airbag
26 Jan 2022	Transport Canada recall 2022022 ^[2] Issued for the model year · Suspension



25 Aug 2026 Listed for sale, Saint-Basile-Le-Grand, QC^[5]
Honda St-Basile · asking \$33,789

29 Oct 2026 Listing last updated^[5]
asking \$33,789

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 8 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

