Register entry, as of 27 October 2026 Listed for sale Record ID 38b8a30136d7

2022 Audi S5 quattro Prestige

3.0 L, 6 cylinders · AWD · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WAU	B4CF5	7	N	A	026420
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Audi Ag	S5 · 3.0 L	Computes	2022	Ingolstadt	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.0 L, 6 cylinders
Make	Audi	Fuel	Gasoline
Model	S5	Drive	AWD
Trim	quattro Prestige	Maker	AUDI AG
Body	Hatchback	Plant	Ingolstadt, Baden-WüRttemberg, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/s5/2022

2 recalls listed by Transport Canada for this model year

Tires

2024487 21 Aug 2024

Issue: Certain tires may have a defect that could cause the tread to separate from the belts. If this happens, the tire could fail. Note: This recall only affects tires with date codes between 1921 and 3224. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Continental Tire will notify registered owners by mail to advise you of this problem. You should contact a Continental Tire dealer if you have tires with these date codes or if you need help inspecting them. All tires affected by this recall will be replaced. For Audi owners, Audi will notify owners by mail and advise you to take your vehicle to an Audi dealership to inspect and, if necessary, replace any affected tires.

Visual system

2022611 26 Oct 2022

Issue: On certain vehicles, the infotainment main unit in the center console could fail. If this happens, the display screen will not turn on when you start the vehicle and the rearview camera image will not appear when backing up. Canadian regulations require the rearview image to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealership to replace the infotainment unit.

Listed for the model year, not checked against your VIN. Audi confirms which apply.
Check your VIN with Audi Canada or call a Audi dealer with your VIN.
www.audi.ca/en/recalls/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $44,990[5], $4,993 over the median of $39,997[4].

Lowest ask	$35,992
Middle half	$38,477 – $44,990
Median ask	$39,997
This car	$44,990

Same model year · 13 live listings · as of 27 Oct 2026

OTHER 2022 AUDI S5 LISTINGS [5]

St-Jean-Sur-Richelieu, QC · 64,185 km	$40,495
Carignan, QC · 102,923 km	$35,992
Carignan, QC · 124,864 km	$35,992
Saint-Basile-le-Grand, QC · 72,767 km	$39,990
Carignan, QC · 104,504 km	$34,998
Oakville, ON · 108,366 km	$36,888

§4 EVENTS

2022	Model year 2022[1] Assembly plant Ingolstadt, Baden-WüRttemberg, Germany
26 Oct 2022	Transport Canada recall 2022611[2] Issued for the model year · Visual system
21 Aug 2024	Transport Canada recall 2024487[2] Issued for the model year · Tires
3 Jun 2026	Listed for sale, Scarborough, ON[5] Velocity Automotive · asking $44,990
27 Oct 2026	Listing last updated[5] asking $44,990

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 13 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.