

Register entry, as of 26 October 2026

Listed for sale

Record ID 212ba4b9ac7a

2013 Audi S8

4.0 L, 8 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER ^[1]**WAU D2AFD 9 D N 016585**

WMI 1-3

Audi Ag

DESCRIPTOR 4-8

S8 · 4.0 L

CHECK 9

Computes

YEAR 10

2013

PLANT 11

Neckarsulm

SERIAL 12-17

Build sequence

§1 IDENTITY ^[1]

Model year	2013	Engine	4.0 L, 8 cylinders
Make	Audi	Fuel	Gasoline
Model	S8	Drive	Not in the decode
Trim	Not in the decode	Maker	AUDI AG
Body	Sedan	Plant	Neckarsulm, Germany

§2 OBLIGATIONS ^[2]

cardog.app/tools/recalls/audi/s8/2013

5 recalls listed by Transport Canada for this model year

Engine	2022133	23 Mar 2022
Issue: On certain vehicles, the oil strainer for the turbocharger oil supply could get blocked. If this happens, a turbocharger could fail. This could cause loss of engine power and/or cause the engine to stall. Note: This problem could cause different warning messages to display or the engine oil warning light to turn on. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: Audi will notify owners by mail and instruct you to take your vehicle to a dealership to replace the oil strainer for the turbocharger oil supply. The dealer will also inspect and document the performance of the boost pressure system and change the engine oil.		
Structure	2020308	7 Jul 2020
Issue: On certain vehicles, the engine compartment seal may become loose over time and fall into the engine compartment. If this happens, the seal could contact a hot surface in the engine compartment. Safety Risk: A rubber seal that falls onto a hot surface could cause a fire. Corrective Action: The company will notify owners by mail and instruct you to take your vehicle to a dealer to install a retaining plate on the engine compartment seal.		
Fuel system	2019040	28 Jan 2019
Issue: On certain vehicles, the fuel line to the high-pressure fuel pump could leak. This may cause a gasoline odour or leak. Safety Risk: Leaking fuel, in the presence of an ignition source, creates the risk of a fire. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer for repair. A fuel pressure damper will be installed in the low pressure fuel supply located inside the fuel tank.		



Fuel system

2018344 26 Jun 2018

On certain vehicles, the fuel supply line for the high pressure fuel pump may become porous over time. This could cause a fuel smell or a fuel leak, which in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will replace the fuel line.

Accessories

2013321 23 Sep 2013

On certain vehicle the sunroof may have been manufactured incorrectly and could be susceptible to breakage. Sunroof glass panel breakage, while the vehicle is in motion, could cause driver distraction, which could result in a crash causing property damage and/or personal injury. Additionally, broken glass inside the vehicle could pose a risk of injury to vehicle occupants. Correction: Dealers will replace the sunroof glass panel.

Listed for the model year, not checked against your VIN. Audi confirms which apply.

Check your VIN with Audi Canada or call a Audi dealer with your VIN.

www.audi.ca/en/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$18,995^[5], \$3,001 under the median of \$21,996^[4].



Lowest ask	\$18,995
Middle half	\$20,496 – \$23,496
Median ask	\$21,996
This car	\$18,995

Same model year · 2 live listings · as of 26 Oct 2026

OTHER 2013 AUDI S8 LISTINGS [5]

Kitchener, ON · 154,233 km \$24,997

§4 EVENTS

2013	Model year 2013 ^[1] Assembly plant Neckarsulm, Germany
23 Sep 2013	Transport Canada recall 2013321 ^[2] Issued for the model year · Accessories
26 Jun 2018	Transport Canada recall 2018344 ^[2] Issued for the model year · Fuel system
28 Jan 2019	Transport Canada recall 2019040 ^[2] Issued for the model year · Fuel system
7 Jul 2020	Transport Canada recall 2020308 ^[2] Issued for the model year · Structure
23 Mar 2022	Transport Canada recall 2022133 ^[2] Issued for the model year · Engine



6 Jul 2026 Listed for sale, North York, ON^[5]
CAR CONNECTION TORONTO · asking \$18,995

26 Oct 2026 Listing last updated^[5]
asking \$18,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 2 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

