Register entry, as of 5 November 2026 Listed for sale Record ID 85c1bbea389b

2015 Audi A6 quattro Prestige

3.0 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WAU	HGCFC	3	F	N	011049
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Audi Ag	A6 · 3.0 L	Computes	2015	Neckarsulm	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.0 L, 6 cylinders
Make	Audi	Fuel	Gasoline
Model	A6	Drive	AWD
Trim	quattro Prestige	Maker	AUDI AG
Body	Sedan	Plant	Neckarsulm, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/audi/a6/2015

3 recalls listed by Transport Canada for this model year

Electrical — 2018680 — 5 Dec 2018

On certain vehicles, the auxiliary heater connector may not have been properly inserted into the auxiliary heater. This could lead to increased resistance in the auxiliary heater circuit, increasing the risk of fire, causing injury and/or damage to property. Correction: Dealers will inspect and replace the auxiliary heater and connector if necessary.

Electrical — 2018174 — 11 Apr 2018

On certain vehicles equipped with a 2.0L TFSI engine, the electric coolant pump could experience a short circuit and/or overheat. A short circuit or overheating of the pump could increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will unplug the electric coolant pump and update the coolant pump software to mitigate the risk of fire as an interim measure. When parts become available, dealers will replace the electric coolant pump, and install an updated coolant pump software.

Engine — 2017002 — 4 Jan 2017


On certain vehicles equipped with a 2.0L TFSI engine, the coolant pump could become blocked by debris from the cooling system. This could lead to the pump overheating and could increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will update vehicle software which deactivates the power supply to the coolant pump if the pump becomes blocked with debris. The driver will be notified of the blocked coolant pump through the illumination of the Electronic Power Control (EPC) lamp.

> Listed for the model year, not checked against your VIN. Audi confirms which apply.
> Check your VIN with Audi Canada or call a Audi dealer with your VIN.
> www.audi.ca/en/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $10,999[5], the median[4].



Lowest ask	$6,999
Middle half	$8,999 – $15,498
Median ask	$10,999
This car	$10,999

Same model year · 3 live listings · as of 5 Nov 2026

OTHER 2015 AUDI A6 LISTINGS [5]

Scarborough, ON · 235,000 km	$6,999

§4 EVENTS

2015	Model year 2015[1] Assembly plant Neckarsulm, Germany
4 Jan 2017	Transport Canada recall 2017002[2] Issued for the model year · Engine
11 Apr 2018	Transport Canada recall 2018174[2] Issued for the model year · Electrical
5 Dec 2018	Transport Canada recall 2018680[2] Issued for the model year · Electrical
1 Nov 2026	Listed for sale, Kitchener, ON[5] Fahad Khan United Motorz Inc. · asking $10,999
5 Nov 2026	Listing last updated[5] asking $10,999

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 3 live listings, as of 5 Nov 2026
[5] Live public dealer listings on Cardog, as of 5 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.