

Register entry, as of 27 October 2026

Listed for sale

Record ID 0274b403c827

# 2013 Audi A4 quattro Prestige

2.0 L, 4 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**WAU KFCFL 7 D N 038762**

WMI 1-3

Audi Ag

DESCRIPTOR 4-8

A4 · 2.0 L

CHECK 9

Computes

YEAR 10

2013

PLANT 11

Neckarsulm

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                  |        |                     |
|------------|------------------|--------|---------------------|
| Model year | 2013             | Engine | 2.0 L, 4 cylinders  |
| Make       | Audi             | Fuel   | Gasoline            |
| Model      | A4               | Drive  | AWD                 |
| Trim       | quattro Prestige | Maker  | AUDI AG             |
| Body       | Sedan            | Plant  | Neckarsulm, Germany |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/audi/a4/2013](https://cardog.app/tools/recalls/audi/a4/2013)

## 4 recalls listed by Transport Canada for this model year

### Electrical

2018174 11 Apr 2018

On certain vehicles equipped with a 2.0L TFSI engine, the electric coolant pump could experience a short circuit and/or overheat. A short circuit or overheating of the pump could increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will unplug the electric coolant pump and update the coolant pump software to mitigate the risk of fire as an interim measure. When parts become available, dealers will replace the electric coolant pump, and install an updated coolant pump software.

### Electrical

2017483 6 Oct 2017

On certain vehicles, the contacts within the electrical connector of the auxiliary heater could corrode. This could cause the auxiliary heater to fail and/or cause the wires to overheat and melt. If the wires were to melt, it could lead to an open circuit and/or overheating, which could increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will replace the auxiliary heater and update vehicle software as necessary.

### Engine

2017002 4 Jan 2017

On certain vehicles equipped with a 2.0L TFSI engine, the coolant pump could become blocked by debris from the cooling system. This could lead to the pump overheating and could increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will update vehicle software which deactivates the power supply to the coolant pump if the pump becomes blocked with debris. The driver will be notified of the blocked coolant pump through the illumination of the Electronic Power Control (EPC) lamp.



**Airbag**

2014477 23 Oct 2014

On certain vehicles, it is possible that the front airbags may not deploy in a crash as designed, due to an improper algorithm/coding within the airbag control module. Front seat occupants may not have the intended protection from the frontal airbag system in crash events where second stage deployment is warranted. This could increase the risk of injury to the front seat occupants. Correction: Dealers will adjust the airbag control unit deployment parameter.

Listed for the model year, not checked against your VIN. Audi confirms which apply.

Check your VIN with Audi Canada or call a Audi dealer with your VIN.

[www.audi.ca/en/recalls/](http://www.audi.ca/en/recalls/)

**§3 VALUE** [3]

This car asks \$17,980<sup>[4]</sup>, \$7,485 over the median of \$10,495<sup>[3]</sup>.



|             |                    |
|-------------|--------------------|
| Lowest ask  | \$4,500            |
| Middle half | \$7,838 – \$16,187 |
| Median ask  | \$10,495           |
| This car    | \$17,980           |

Same model year · 14 live listings · as of 27 Oct 2026

**OTHER 2013 AUDI A4 LISTINGS** [4]

|                            |          |
|----------------------------|----------|
| Toronto, ON · 140,272 km   | \$9,995  |
| Toronto, ON · 209,545 km   | \$7,950  |
| Longueuil, QC · 208,526 km | \$7,495  |
| Toronto, ON · 140,272 km   | \$9,995  |
| Victoria, BC · 102,400 km  | \$17,525 |
| Victoria, BC · 102,400 km  | \$17,525 |

**§4 EVENTS**

|             |                                                                                                 |
|-------------|-------------------------------------------------------------------------------------------------|
| 2013        | Model year 2013 <sup>[1]</sup><br>Assembly plant Neckarsulm, Germany                            |
| 23 Oct 2014 | Transport Canada recall 2014477 <sup>[2]</sup><br>Issued for the model year · Airbag            |
| 4 Jan 2017  | Transport Canada recall 2017002 <sup>[2]</sup><br>Issued for the model year · Engine            |
| 6 Oct 2017  | Transport Canada recall 2017483 <sup>[2]</sup><br>Issued for the model year · Electrical        |
| 11 Apr 2018 | Transport Canada recall 2018174 <sup>[2]</sup><br>Issued for the model year · Electrical        |
| 27 Nov 2025 | Listed for sale, Vancouver, BC <sup>[4]</sup><br>Granville Island Auto Centre · asking \$17,980 |



24 Oct 2026      Listing last updated<sup>[4]</sup>  
asking \$17,980

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 14 live listings, as of 27 Oct 2026

[4] Live public dealer listings on Cardog, as of 27 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

