

Register entry, as of 26 October 2026

Listed for sale

Record ID 43bbf355cd4b

# 2014 Audi A5 quattro Premium Plus

2.0 L, 4 cylinders · AWD · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**WAU MFBFR 5 E A 030451**WMI 1-3  
Audi AgDESCRIPTOR 4-8  
A5 · 2.0 LCHECK 9  
ComputesYEAR 10  
2014PLANT 11  
IngolstadtSERIAL 12-17  
Build sequence

## §1 IDENTITY [1]

|            |                      |        |                     |
|------------|----------------------|--------|---------------------|
| Model year | 2014                 | Engine | 2.0 L, 4 cylinders  |
| Make       | Audi                 | Fuel   | Gasoline            |
| Model      | A5                   | Drive  | AWD                 |
| Trim       | quattro Premium Plus | Maker  | AUDI AG             |
| Body       | Coupe                | Plant  | Ingolstadt, Germany |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/audi/a5/2014](https://cardog.app/tools/recalls/audi/a5/2014)

## 3 recalls listed by Transport Canada for this model year

**Electrical** 2018174 11 Apr 2018

On certain vehicles equipped with a 2.0L TFSI engine, the electric coolant pump could experience a short circuit and/or overheat. A short circuit or overheating of the pump could increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will unplug the electric coolant pump and update the coolant pump software to mitigate the risk of fire as an interim measure. When parts become available, dealers will replace the electric coolant pump, and install an updated coolant pump software.

**Electrical** 2017483 6 Oct 2017

On certain vehicles, the contacts within the electrical connector of the auxiliary heater could corrode. This could cause the auxiliary heater to fail and/or cause the wires to overheat and melt. If the wires were to melt, it could lead to an open circuit and/or overheating, which could increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will replace the auxiliary heater and update vehicle software as necessary.

**Engine** 2017002 4 Jan 2017

On certain vehicles equipped with a 2.0L TFSI engine, the coolant pump could become blocked by debris from the cooling system. This could lead to the pump overheating and could increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will update vehicle software which deactivates the power supply to the coolant pump if the pump becomes blocked with debris. The driver will be notified of the blocked coolant pump through the illumination of the Electronic Power Control (EPC) lamp.

Listed for the model year, not checked against your VIN. Audi confirms which apply.

Check your VIN with Audi Canada or call a Audi dealer with your VIN.

[www.audi.ca/en/recalls/](https://www.audi.ca/en/recalls/)



United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

### §3 VALUE <sup>[4]</sup>

This car asks \$14,599<sup>[5]</sup>, \$1,603 over the median of \$12,996<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$9,800             |
| Middle half | \$10,998 – \$14,697 |
| Median ask  | \$12,996            |
| This car    | \$14,599            |

Same model year · 12 live listings · as of 26 Oct 2026

#### OTHER 2014 AUDI A5 LISTINGS <sup>[5]</sup>

|                                   |          |
|-----------------------------------|----------|
| North York, ON · 156,979 km       | \$14,990 |
| Calgary, AB · 143,583 km          | \$14,991 |
| Vaudreuil-Dorion, QC · 175,882 km | \$12,990 |
| Mississauga, ON · 113,940 km      | \$13,995 |
| Toronto, ON · 162,323 km          | \$12,999 |
| Ottawa, ON · 167,434 km           | \$10,999 |

### §4 EVENTS

|             |                                                                                          |
|-------------|------------------------------------------------------------------------------------------|
| 2014        | Model year 2014 <sup>[1]</sup><br>Assembly plant Ingolstadt, Germany                     |
| 4 Jan 2017  | Transport Canada recall 2017002 <sup>[2]</sup><br>Issued for the model year · Engine     |
| 6 Oct 2017  | Transport Canada recall 2017483 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 11 Apr 2018 | Transport Canada recall 2018174 <sup>[2]</sup><br>Issued for the model year · Electrical |
| 11 Jun 2026 | Listed for sale, Oakville, ON <sup>[5]</sup><br>AKM AUTOMOTIVE LTD · asking \$14,599     |
| 26 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$14,599                                   |

### §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.



SOURCES

- [1] Cardog identity register, decoded from the VIN
- [2] Transport Canada recall database, listed for the model year
- [3] NHTSA recall records (United States), listed for the model year
- [4] Cardog market quote, same model year, 12 live listings, as of 26 Oct 2026
- [5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

