Register entry, as of 27 October 2026 Listed for sale Record ID 4350a6d4c016

2023 BMW iX

Electric

VEHICLE IDENTIFICATION NUMBER [1]

WB5	13CF0	X	P	C	M57973
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Bmw Ag	iX	Computes	2023	Dingolfing	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	Not in the decode
Make	BMW	Fuel	Electric
Model	iX	Drive	Not in the decode
Trim	Not in the decode	Maker	BMW AG
Body	Not in the decode	Plant	Dingolfing, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/ix/2023

8 recalls listed by Transport Canada for this model year

High voltage

2025320 13 Jun 2025

Issue: On certain vehicles, a problem with the electric drive motor software could cause the vehicle to enter a fail-safe mode. If this happens, there could be a loss of power to the wheels. Note: This problem would cause a warning light to turn on and a warning message to be displayed. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the electric drive motor software. Alternatively, you may schedule an appointment to have the update performed at a BMW dealership.

Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

High voltage

2023363 28 Jun 2023

Issue: On a small number of vehicles, the combined charging unit (CCU) may not have been assembled correctly. As a result, power from the high-voltage battery could be interrupted while driving. If this happens, the vehicle could stall and lose power to the wheels. Safety Risk: A sudden loss of power could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and advise you to take your vehicle to a dealership to replace the high-voltage battery combined charging unit (CCU).

Accessories

2023333 7 Jun 2023

Issue: On certain vehicles, the driver's hand could accidently reactivate the cruise control while turning at low speeds. If this happens, the vehicle could accelerate and cause an unexpected speed increase. Safety Risk: An unexpected increase in vehicle speed could create the risk of a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealership to update the vehicle software.

Airbag

2023061 14 Feb 2023

Issue: On certain vehicles, the driver-front airbag may not inflate correctly in a crash. Safety Risk: An airbag that does not inflate correctly could create an increased risk of injury in a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealership to replace the driver-front airbag.

High voltage

2022734 20 Dec 2022

Issue: On certain vehicles, a software problem could cause the high-voltage battery electronic control unit to reset. As a result, the high-voltage system could disconnect while driving. If this happens, there could be a sudden loss of power to the wheels. Note: If this happens, you may see a warning message on the instrument panel. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to update the high-voltage battery electronic control unit software.

2 more on the model-year record, cardog.app/tools/recalls/bmw/ix/2023

> Listed for the model year, not checked against your VIN. BMW confirms which apply.
> Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $58,995[5], $4,023 over the median of $54,972[4].

Lowest ask	$39,998
Middle half	$51,212 – $58,174
Median ask	$54,972
This car	$58,995

Same configuration · 20 live listings · as of 27 Oct 2026

OTHER 2023 BMW IX LISTINGS [5]

Woodbridge, ON · 89,808 km	$65,995
Kelowna, BC · 63,752 km	$59,999
Sainte-Rose, QC · 100,683 km	$43,900
Vancouver, BC · 42,800 km	$67,900
Vancouver, BC · 72,000 km	$62,900
Vancouver, BC · 30,500 km	$67,900

§4 EVENTS

2023 Model year 2023[1]
Assembly plant Dingolfing, Germany

7 Jul 2022	Transport Canada recall 2022364[2] Issued for the model year · Airbag
7 Jul 2022	Transport Canada recall 2022363[2] Issued for the model year · Lights and instruments
20 Dec 2022	Transport Canada recall 2022734[2] Issued for the model year · High voltage
14 Feb 2023	Transport Canada recall 2023061[2] Issued for the model year · Airbag
7 Jun 2023	Transport Canada recall 2023333[2] Issued for the model year · Accessories
28 Jun 2023	Transport Canada recall 2023363[2] Issued for the model year · High voltage
15 Aug 2024	Transport Canada recall 2024544[2] Issued for the model year · Label
13 Jun 2025	Transport Canada recall 2025320[2] Issued for the model year · High voltage
26 Oct 2026	Listed for sale, Burnaby, BC[5] Destination Honda Burnaby · asking $58,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 20 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.