Register entry, as of 24 November 2026 Listed for sale Record ID 922e2a41d7d1

# 2019 BMW Z4 sDrive30i

2.0 L, 4 cylinders · RWD · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WBA | HF3C5 | 6 | K | W | W48840 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Bmw Ag | Z4 · 2.0 L | Computes | 2019 | Graz | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 2.0 L, 4 cylinders |
| Make | BMW | Fuel | Gasoline |
| Model | Z4 | Drive | RWD |
| Trim | sDrive30i | Maker | BMW AG |
| Body | Convertible | Plant | Graz, Austria |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/bmw/z4/2019

7 recalls listed by Transport Canada for this model year

### Lights and instruments

2026285 9 Jun 2026

Issue: Under certain conditions, the windshield wiping system may not meet certain requirements of Canadian regulations. Safety Risk: This small error does not affect safety. Corrective Actions: This is not a recall. BMW has made changes to ensure that all new vehicles meet Canadian regulations.

### Electrical

2025499 23 Sep 2025

Issue: On certain vehicles, water could leak into the starter relay and cause it to corrode. If this happens, the relay could short circuit and the starter could overheat. Safety Risk: A short circuit and/or a starter that overheats can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, BMW advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed. BMW will notify owners by mail and advise you to take your vehicle to a dealership to replace the engine starter.

### Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Lights and instruments

2020395 27 Aug 2020

Issue: On certain vehicles, the headlight adjustment plugs were not properly installed when the vehicle was assembled. As a result, the headlights may be adjusted horizontally. Canadian regulations do not allow for horizontal headlight adjustment unless the vehicle is equipped with a built-in aiming device. Safety Risk: Headlights that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and could increase the risk of a crash. Corrective Actions: BMW will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the headlights. If an incorrect adjustment plug is found, it will be replaced with the correct plug.

### Steering

2020267 16 Jun 2020

Issue: On certain vehicles, high temperatures and excessive vibration could cause damage to the steering tie rods. If this happens, the tie rods could break. This could result in a loss of steering control. Safety Risk: A loss of steering control could create a risk of a crash. Corrective Actions: BMW will notify owners by mail and instruct you take your vehicle to a dealer to replace the steering tie rods.

### Visual system

2019480 1 Oct 2019

Issue: On certain vehicles, the rearview camera does not return to the default settings when it turns on. This could make the rearview image difficult to see if a driver had previously adjusted the camera display brightness at or near the lowest setting, and contrast at or near the highest setting. Canadian regulations require that the rearview display returns to the default view each time the camera is turned on. Safety Risk: Reduced rear visibility could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to update the software for the rearview camera. Drivers are recommended not to adjust the display brightness at or near the lowest setting, and contrast at or near the highest setting, until this recall is completed.

1 more on the model-year record, cardog.app/tools/recalls/bmw/z4/2019

> Listed for the model year, not checked against your VIN. BMW confirms which apply. Check your VIN with BMW Canada or call a BMW dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $42,979[5], the median[4].




| | |
|---|---|
| Lowest ask | $42,979 |
| Middle half | $42,979 – $42,979 |
| Median ask | $42,979 |
| This car | $42,979 |

Same model year · 1 live listings · as of 24 Nov 2026

## §4 EVENTS

| | |
|---|---|
| 2019 | Model year 2019[1]<br>Assembly plant Graz, Austria |
| 13 Feb 2019 | Transport Canada recall 2019069[2]<br>Issued for the model year · Powertrain |
| 1 Oct 2019 | Transport Canada recall 2019480[2]<br>Issued for the model year · Visual system |

| | |
|---|---|
| 16 Jun 2020 | **Transport Canada recall 2020267**[2]<br>Issued for the model year · Steering |
| 27 Aug 2020 | **Transport Canada recall 2020395**[2]<br>Issued for the model year · Lights and instruments |
| 15 Aug 2024 | **Transport Canada recall 2024544**[2]<br>Issued for the model year · Label |
| 23 Sep 2025 | **Transport Canada recall 2025499**[2]<br>Issued for the model year · Electrical |
| 9 Jun 2026 | **Transport Canada recall 2026285**[2]<br>Issued for the model year · Lights and instruments |
| 9 Oct 2026 | **Listed for sale, North York, ON**[5]<br>SUPERB AUTO SALES · asking $42,979 |
| 24 Nov 2026 | **Listing last updated**[5]<br>asking $42,979 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 1 live listings, as of 24 Nov 2026

[5] Live public dealer listings on Cardog, as of 24 Nov 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.