

Register entry, as of 28 October 2026

Listed for sale

Record ID b2eadc2a8476

2003 Mercedes-Benz CL-Class CL500

5.0 L, 8 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDB PJ75J 2 3 A 034654

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

CL-Class · 5.0 L

CHECK 9

Computes

YEAR 10

2003

PLANT 11

Germany

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2003	Engine	5.0 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	CL-Class	Drive	Not in the decode
Trim	CL500	Maker	Mercedes-Benz Cars
Body	Coupe	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/cl-class/2003

4 recalls listed by Transport Canada for this model year

Other 2008290 15 Aug 2008

Certain vehicles equipped with Active Body Control (ABC) the sensors on the front struts may not operate within tolerances. As such, the sensor signal may not be accurately transmitted to the Electronic Control Unit (ECU). A variation in the transmitted values can result in one front strut adjusting to a value while the other does not adjust and presenting the driver with an uneven front suspension. This situation could have an effect on the vehicle's directional stability, possibly resulting in a vehicle crash with injuries or death. Correction: Dealers will inspect and replace affected AZ-sensors

Steering 2007195 14 Jun 2007

On certain vehicles equipped with an 8-cylinder engine, corrosion may occur in the inner steel portions of the Active Body Control's high pressure distribution hose due to extensive exposure to humidity. This may result in ABC hydraulic fluid leakage near the catalytic converter which could cause a fire. Correction: Dealers will install a corrosion resistant ABC high-pressure distribution hose.

Other 2004184 3 Jun 2004

On certain vehicles, the trunk lid springs could fail in the closed trunk lid position due to extensive exposure to very high temperatures. This failure only occurs in the closed position and causes the trunk lid to fail to spring open upon being unlocked, thereby providing warning to the owner of the broken spring condition. Correction: Dealers will replace the trunk lid springs.

Brakes 2004153 6 May 2004

On certain vehicles equipped with a 12-cylinder engine, corrosion may occur in the inner steel portions of the Active Body Control's high pressure distribution hose due to extensive exposure to humidity. This may result in ABC hydraulic fluid leakage near the catalytic converter which could cause a fire. Correction: Dealers will install a corrosion resistant ABC high-pressure distribution hose.



Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$12,575^[5], the median^[4].



Lowest ask	\$12,575
Middle half	\$12,575 – \$12,575
Median ask	\$12,575
This car	\$12,575

Same model year · 1 live listings · as of 28 Oct 2026

§4 EVENTS

2003	Model year 2003 ^[1] Assembly plant Germany
6 May 2004	Transport Canada recall 2004153 ^[2] Issued for the model year · Brakes
3 Jun 2004	Transport Canada recall 2004184 ^[2] Issued for the model year · Other
14 Jun 2007	Transport Canada recall 2007195 ^[2] Issued for the model year · Steering
15 Aug 2008	Transport Canada recall 2008290 ^[2] Issued for the model year · Other
25 Oct 2026	Listed for sale, Cowansville, QC ^[5] Ford Deragon · asking \$12,575
28 Oct 2026	Listing last updated ^[5] asking \$12,575

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.



SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

