

Register entry, as of 29 October 2026

Listed for sale

Record ID 4d65407ec8be

2018 Mercedes-Benz GLC-Class GLC 300-4M

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDC 0G4KB 8 J V 055490

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

GLC-Class · 2.0 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Uusikaupunki

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GLC-Class	Drive	Not in the decode
Trim	GLC 300-4M	Maker	Mercedes-Benz Cars
Body	Sport Utility Vehicle	Plant	Uusikaupunki, Finland

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/glc-class/2018

13 recalls listed by Transport Canada for this model year

Structure

2023673 15 Dec 2023

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Note: This is an expansion of Transport Canada recall 2021-170. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the front roof panel.

Visual system

2021291 14 May 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Structure

2021170 22 Mar 2021

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front roof panel.



Accessories

2021041 1 Feb 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to update the head unit software.

Electrical

2020614 12 Dec 2020

Issue: On certain vehicles, the power supply cable to the starter may have been attached incorrectly. As a result, the power cable could contact the starter housing. This can damage the cable, and could result in a short circuit. Safety Risk: A short circuit could cause the vehicle to stall and create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to check the cable connections to the starter and correct them, if necessary.

Seats and restraints

2019554 6 Nov 2019

Issue: On certain vehicles, there may be a problem with the front seat belt buckles. This could cause the seat belt warnings to turn on, even if the front seat belts are buckled. If the driver ignores these warnings, the PRE-SAFE and airbag systems may not function properly. Safety Risk: A seat belt pretensioner or airbag system that does not work properly in a crash could increase the risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to check the front seat belt buckles and replace them if necessary.


7 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/glc-class/2018

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks \$19,800^[4], \$1,144 under the median of \$20,944^[3].



Lowest ask	\$17,632
Middle half	\$19,932 – \$23,416
Median ask	\$20,944
This car	\$19,800

Same configuration · 31 live listings · as of 29 Oct 2026

OTHER 2018 MERCEDES-BENZ GLC-CLASS LISTINGS [4]

Montréal, QC · 98,000 km	\$28,490
Vancouver, BC · 81,399 km	\$26,900
Regina, SK · 99,301 km	\$24,990
Mississauga, ON · 86,121 km	\$28,992
North Vancouver, BC · 153,000 km	\$18,950
North York, ON · 144,781 km	\$18,985

§4 EVENTS

2018 Model year 2018^[1]
Assembly plant Uusikaupunki, Finland



10 Oct 2017	Transport Canada recall 2017490 ^[2] Issued for the model year · Airbag
15 Nov 2017	Transport Canada recall 2017556 ^[2] Issued for the model year · Accessories
16 Mar 2018	Transport Canada recall 2018136 ^[2] Issued for the model year · Seats and restraints
11 Sep 2018	Transport Canada recall 2018491 ^[2] Issued for the model year · Lights and instruments
3 Oct 2018	Transport Canada recall 2018541 ^[2] Issued for the model year · Seats and restraints
28 Nov 2018	Transport Canada recall 2018656 ^[2] Issued for the model year · Airbag
20 Dec 2018	Transport Canada recall 2018723 ^[2] Issued for the model year · Airbag
6 Nov 2019	Transport Canada recall 2019554 ^[2] Issued for the model year · Seats and restraints
12 Dec 2020	Transport Canada recall 2020614 ^[2] Issued for the model year · Electrical
1 Feb 2021	Transport Canada recall 2021041 ^[2] Issued for the model year · Accessories
22 Mar 2021	Transport Canada recall 2021170 ^[2] Issued for the model year · Structure
14 May 2021	Transport Canada recall 2021291 ^[2] Issued for the model year · Visual system
15 Dec 2023	Transport Canada recall 2023673 ^[2] Issued for the model year · Structure
24 Oct 2026	Listed for sale, Whitchurch-Stouffville, ON ^[4] Kia Stouffville · asking \$19,800
28 Oct 2026	Listing last updated ^[4] asking \$19,800

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [3] Cardog market quote, same configuration, 31 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 29 Oct 2026 |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

