

Register entry, as of 28 October 2026

Listed for sale

Record ID 8979321b8ec6

2017 Mercedes-Benz GLC-Class GLC300 Base-4M

2.0 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDC 0G4KB 9 H V 000704

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

GLC-Class · 2.0 L

CHECK 9

Computes

YEAR 10

2017

PLANT 11

Uusikaupunki

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GLC-Class	Drive	Not in the decode
Trim	GLC300 Base-4M	Maker	Mercedes-Benz Cars
Body	Sport Utility Vehicle	Plant	Uusikaupunki, Finland

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/glc-class/2017

11 recalls listed by Transport Canada for this model year

Structure

2023673 15 Dec 2023

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Note: This is an expansion of Transport Canada recall 2021-170. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the front roof panel.

Structure

2021170 22 Mar 2021

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front roof panel.

Visual system

2019673 11 Jun 2019

Issue: On certain vehicles, the rear-side glass may not be properly marked with its safety rating. Canadian regulations require a marking to identify the type of glass that is used. Safety Risk: This error is unlikely to affect safety. Corrective Action: This is not a recall. This notice is for information only. The company has made changes to ensure that all new vehicles have glass that is marked correctly.



Steering

2018724 20 Dec 2018

On certain vehicles originally sold or currently registered in areas of heavy road salt usage during winter months (Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the bolts that attach the electric power steering assist motor to the steering gear housing may corrode and break. This could cause a loss of power steering assist. The resulting increase in steering effort could create the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the mounting bolts and apply a corrosion protection coating to the gear housing and bolts. If the bolts cannot be removed, a replacement steering gear will be installed.

Seats and restraints

2018541 3 Oct 2018

On certain vehicles, the seat belt latch plate in the second seating row outboard seats might retract into the area between the C-pillar paneling and the rear side paneling. This could hinder the access to the seat belt latch plate for the outboard seat occupants. If a rear seat passenger does not fasten the seat belt, the risk of injury in the event of a crash could increase. Correction: Dealers will add a buffer element to the C-pillar paneling. Note: This is an expansion of recall 2018-136.

Seats and restraints

2018136 16 Mar 2018

On certain vehicles, the seat belt latch plate in the second seating row outboard seats might retract into the area between the C-pillar paneling and the rear side paneling. This could hinder the access to the seat belt latch plate for the outboard seat occupants. If a rear seat passenger does not fasten the seat belt, the risk of injury in the event of a crash could increase. Correction: Dealers will add a buffer element to the C-pillar paneling.


5 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/glc-class/2017

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks \$21,995^[4], \$3,099 over the median of \$18,896^[3].



Lowest ask	\$14,800
Middle half	\$17,987 – \$20,960
Median ask	\$18,896
This car	\$21,995

Same configuration · 26 live listings · as of 28 Oct 2026

OTHER 2017 MERCEDES-BENZ GLC-CLASS LISTINGS [4]

Toronto, ON · 135,051 km	\$17,995
Richmond, BC · 110,452 km	\$17,999
Halton Hills, ON · 176,478 km	\$14,999
North York, ON · 195,776 km	\$14,995
North York, ON · 87,389 km	\$19,985
Mississauga, ON · 129,368 km	\$21,495

§4 EVENTS

2017

Model year 2017^[1]

Assembly plant Uusikaupunki, Finland



9 Feb 2017	Transport Canada recall 2017062 ^[2] Issued for the model year · Engine
11 Apr 2017	Transport Canada recall 2017205 ^[2] Issued for the model year · Seats and restraints
10 Oct 2017	Transport Canada recall 2017490 ^[2] Issued for the model year · Airbag
15 Nov 2017	Transport Canada recall 2017556 ^[2] Issued for the model year · Accessories
19 Dec 2017	Transport Canada recall 2017645 ^[2] Issued for the model year · Lights and instruments
16 Mar 2018	Transport Canada recall 2018136 ^[2] Issued for the model year · Seats and restraints
3 Oct 2018	Transport Canada recall 2018541 ^[2] Issued for the model year · Seats and restraints
20 Dec 2018	Transport Canada recall 2018724 ^[2] Issued for the model year · Steering
11 Jun 2019	Transport Canada recall 2019673 ^[2] Issued for the model year · Visual system
22 Mar 2021	Transport Canada recall 2021170 ^[2] Issued for the model year · Structure
15 Dec 2023	Transport Canada recall 2023673 ^[2] Issued for the model year · Structure
26 Oct 2026	Listed for sale, Mississauga, ON ^[4] Streetsville Hyundai · asking \$21,995
28 Oct 2026	Listing last updated ^[4] asking \$21,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same configuration, 26 live listings, as of 28 Oct 2026

[4] Live public dealer listings on Cardog, as of 28 Oct 2026



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

