Register entry, as of 27 October 2026 Listed for sale Record ID bebdcd9259a4

2015 Mercedes-Benz GLK-Class GLK250 BLUETEC 4-MATIC

2.1 L, 4 cylinders · AWD · Sport Utility Vehicle · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

WDC	GG0EB	2	F	G	418297
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Cars	GLK-Class · 2.1 L	Computes	2015	Germany	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	2.1 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Diesel
Model	GLK-Class	Drive	AWD
Trim	GLK250 BLUETEC 4-MATIC	Maker	Mercedes-Benz Cars
Body	Sport Utility Vehicle	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/glk-class/2015

4 recalls listed by Transport Canada for this model year

Airbag

2018741 28 Dec 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag module. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Steering

2018724 20 Dec 2018

On certain vehicles originally sold or currently registered in areas of heavy road salt usage during winter months (Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the bolts that attach the electric power steering assist motor to the steering gear housing may corrode and break. This could cause a loss of power steering assist. The resulting increase in steering effort could create the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the mounting bolts and apply a corrosion protection coating to the gear housing and bolts. If the bolts bolt cannot be removed, a replacement steering gear will be installed.

Airbag

2017490 10 Oct 2017

On certain vehicles, electrostatic discharge, when combined with a broken clock spring and insufficient grounding of the steering components, could lead to an inadvertent deployment of the driver's frontal airbag. Unintended airbag deployment, in a non-warranted (non-impact) situation, could startle the driver, which could result in a crash causing injury and/or property damage. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will add sufficient grounding to the steering components. Note: A broken clock spring would result in a driver airbag warning message appearing in the instrument cluster, as well as a red airbag warning lamp illuminating.

Engine

2014546 3 Dec 2014

On certain vehicles equipped with four-cylinder diesel engines, the timing chain tensioner gasket could fail, causing an oil leak. If the vehicle is operated in this condition, this could cause engine failure, which would result in a loss of motive power. Oil leaking onto hot engine surfaces could also increase the risk of a fire. These issues could increase the risk of injury and/or damage to property. Correction: Dealers will replace the timing chain tensioner gasket.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $5,999[4], $7,889 under the median of $13,888[3].

Lowest ask	$5,999
Middle half	$12,888 – $15,385
Median ask	$13,888
This car	$5,999

Same configuration · 21 live listings · as of 27 Oct 2026

OTHER 2015 MERCEDES-BENZ GLK-CLASS LISTINGS [4]

Markham, ON · 138,302 km	$12,988
Laval, QC · 79,254 km	$12,888
Calgary, AB · 102,000 km	$18,778
Calgary, AB · 163,307 km	$15,995
North Vancouver, BC · 141,451 km	$16,905
Scarborough, ON · 274,000 km	$7,972

§4 EVENTS

2015	Model year 2015[1] Assembly plant Germany
3 Dec 2014	Transport Canada recall 2014546[2] Issued for the model year · Engine
10 Oct 2017	Transport Canada recall 2017490[2] Issued for the model year · Airbag

20 Dec 2018	Transport Canada recall 2018724[2] Issued for the model year · Steering
28 Dec 2018	Transport Canada recall 2018741[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, Hamilton, ON[4] Auto View · asking $5,999
27 Oct 2026	Listing last updated[4] asking $5,999

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same configuration, 21 live listings, as of 27 Oct 2026

[4] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.