Register entry, as of 7 November 2026 Listed for sale Record ID b7c208eb40d8

2012 Mercedes-Benz GLK-Class GLK350 4-MATIC

3.5 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDC	GG8HB	5	C	F	895723
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Cars	GLK-Class · 3.5 L	Computes	2012	Bremen	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	3.5 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	GLK-Class	Drive	AWD
Trim	GLK350 4-MATIC	Maker	Mercedes-Benz Cars
Body	Sport Utility Vehicle	Plant	Bremen, Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/glk-class/2012

5 recalls listed by Transport Canada for this model year

Airbag

2018741 28 Dec 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag module. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Steering

2018724 20 Dec 2018

On certain vehicles originally sold or currently registered in areas of heavy road salt usage during winter months (Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the bolts that attach the electric power steering assist motor to the steering gear housing may corrode and break. This could cause a loss of power steering assist. The resulting increase in steering effort could create the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the mounting bolts and apply a corrosion protection coating to the gear housing and bolts. If the bolts bolt cannot be removed, a replacement steering gear will be installed.

Airbag

2017490 10 Oct 2017

On certain vehicles, electrostatic discharge, when combined with a broken clock spring and insufficient grounding of the steering components, could lead to an inadvertent deployment of the driver's frontal airbag. Unintended airbag deployment, in a non-warranted (non-impact) situation, could startle the driver, which could result in a crash causing injury and/or property damage. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will add sufficient grounding to the steering components. Note: A broken clock spring would result in a driver airbag warning message appearing in the instrument cluster, as well as a red airbag warning lamp illuminating.

Airbag

2016158 13 Apr 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will replace the front driver air bag module.

Lights and instruments


2012386 14 Nov 2012

Certain vehicles may not comply with Canada Motor Vehicle Safety Standard 108 - Lighting System and Retroreflective Devices. The front parking lamps may exceed the maximum candlepower output specified in the Standard and corresponding Technical Standards Document 108. Correction: A production change has been undertaken to remedy these technical non-compliance conditions. No corrective recall action is required as the technical non-compliance conditions are deemed to be non-safety related.

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $9,989[4], $995 under the median of $10,984[3].



Lowest ask	$8,495
Middle half	$9,618 – $11,994
Median ask	$10,984
This car	$9,989

Same model year · 6 live listings · as of 7 Nov 2026

OTHER 2012 MERCEDES-BENZ GLK-CLASS LISTINGS [4]

Pointe-aux-trembles, QC · 153,500 km	$9,495
Barrie, ON · 192,244 km	$8,495
Scarborough, ON · 146,619 km	$11,999
Oakville, ON · 113,451 km	$18,480
Surrey, BC · 166,000 km	$11,980

§4 EVENTS

2012 Model year 2012[1]
Assembly plant Bremen, Germany

14 Nov 2012	**Transport Canada recall 2012386**[2] Issued for the model year · Lights and instruments
13 Apr 2016	**Transport Canada recall 2016158**[2] Issued for the model year · Airbag
10 Oct 2017	**Transport Canada recall 2017490**[2] Issued for the model year · Airbag
20 Dec 2018	**Transport Canada recall 2018724**[2] Issued for the model year · Steering
28 Dec 2018	**Transport Canada recall 2018741**[2] Issued for the model year · Airbag
1 Jun 2026	**Listed for sale, Calgary, AB**[4] Fine Auto Zone · asking $9,989
6 Nov 2026	**Listing last updated**[4] asking $9,989

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 6 live listings, as of 7 Nov 2026
[4] Live public dealer listings on Cardog, as of 7 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.