Register entry, as of 27 October 2026 Listed for sale Record ID a8cdd8f50a2a

2020 Mercedes-Benz A-Class A220-4M

2.0 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD	3G4FB	6	L	W	042690
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz Cars	A-Class · 2.0 L	Computes	2020	Aguascalientes	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	A-Class	Drive	Not in the decode
Trim	A220-4M	Maker	Mercedes-Benz Cars
Body	Sedan	Plant	Aguascalientes, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/a-class/2020

11 recalls listed by Transport Canada for this model year

Structure

2026364 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away. Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Visual system

2022177 12 Apr 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the rearview camera software.

Steering

2021772 17 Dec 2021

Issue: On certain vehicles, the front subframe could corrode over time. If this happens, suspension or steering parts could eventually detach from it. This could affect steering control. Safety Risk: A loss of steering control could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front subframe (integral carrier) and replace it, if necessary.

Fuel system

2021755 13 Dec 2021

Issue: On certain vehicles, small particles could damage the seals between the fuel rail and fuel injectors. If this happens, there could be a fuel leak in the engine compartment. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel rail and fuel injectors.

Lights and instruments

2021415 5 Jul 2021

Issue: On certain vehicles, a label on the headlamp assembly may contain incorrect information for a service technician. As a result, the headlamps may not get adjusted correctly after a repair. This could cause glare and/or confusion for oncoming drivers. Note: This recall only affects certain vehicles equipped with LED headlamps. Safety Risk: Headlamps that cause glare or confusion for oncoming drivers could increase the risk of a crash. Corrective Action: Mercedez-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the headlamps.

5 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/a-class/2020

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $19,795[4], $5,177 under the median of $24,972[3].

Lowest ask	$19,795
Middle half	$21,120 – $28,245
Median ask	$24,972
This car	$19,795

Same configuration · 8 live listings · as of 27 Oct 2026

OTHER 2020 MERCEDES-BENZ A-CLASS LISTINGS [4]

Quebec, QC · 80,395 km	$30,995
London, ON · 132,000 km	$19,991
Vancouver, BC · 0 km	$25,800
Mississauga, ON · 35,433 km	$25,552
London, ON · 144,078 km	$19,995
Saint-Nicolas (Québec) Canada, QC · 87,002 km	$21,987

§4 EVENTS

2020 Model year 2020[1]
Assembly plant Aguascalientes, Mexico

2 Oct 2019	Transport Canada recall 2019484[2] Issued for the model year · Airbag
14 Feb 2020	Transport Canada recall 2020062[2] Issued for the model year · Lights and instruments
23 Oct 2020	Transport Canada recall 2020507[2] Issued for the model year · Lights and instruments
12 Feb 2021	Transport Canada recall 2021064[2] Issued for the model year · Electrical
14 May 2021	Transport Canada recall 2021291[2] Issued for the model year · Visual system
5 Jul 2021	Transport Canada recall 2021415[2] Issued for the model year · Lights and instruments
13 Dec 2021	Transport Canada recall 2021755[2] Issued for the model year · Fuel system
17 Dec 2021	Transport Canada recall 2021772[2] Issued for the model year · Steering
12 Apr 2022	Transport Canada recall 2022177[2] Issued for the model year · Visual system
20 May 2022	Transport Canada recall 2022263[2] Issued for the model year · Other
24 Jul 2026	Transport Canada recall 2026364[2] Issued for the model year · Structure
15 Oct 2026	Listed for sale, Mississauga, ON[4] Precision Honda · asking $19,795
27 Oct 2026	Listing last updated[4] asking $19,795

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same configuration, 8 live listings, as of 27 Oct 2026
[4] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.