Register entry, as of 28 October 2026 Listed for sale Record ID 94fe49a3f986

# 2013 Mercedes-Benz C-Class C250

1.8 L, 4 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WDD | GJ4HB | 8 | D | G | 090154 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Mercedes-Benz Cars | C-Class · 1.8 L | Computes | 2013 | Germany | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2013 | Engine | 1.8 L, 4 cylinders |
| Make | Mercedes-Benz | Fuel | Gasoline |
| Model | C-Class | Drive | Not in the decode |
| Trim | C250 | Maker | Mercedes-Benz Cars |
| Body | Coupe | Plant | Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/c-class/2013

**6** recalls listed by Transport Canada for this model year

### Airbag

2021514 16 Aug 2021

Issue: On certain vehicles, an incorrect passenger-front airbag may have been installed during a previous repair. As a result, the airbag may not inflate properly in a crash. Safety Risk: An airbag that does not inflate properly can increase the risk of injury in a crash. Corrective Action: Mercedes-Benz will notify owners by mail and instruct you to bring your vehicle to a dealer to replace the passenger-front airbag.

### Airbag

2018741 28 Dec 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag module. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

### Steering

2018724 20 Dec 2018

On certain vehicles originally sold or currently registered in areas of heavy road salt usage during winter months (Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the bolts that attach the electric power steering assist motor to the steering gear housing may corrode and break. This could cause a loss of power steering assist. The resulting increase in steering effort could create the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the mounting bolts and apply a corrosion protection coating to the gear housing and bolts. If the bolts bolt cannot be removed, a replacement steering gear will be installed.

### Airbag

2017490 10 Oct 2017

On certain vehicles, electrostatic discharge, when combined with a broken clock spring and insufficient grounding of the steering components, could lead to an inadvertent deployment of the driver's frontal airbag. Unintended airbag deployment, in a non-warranted (non-impact) situation, could startle the driver, which could result in a crash causing injury and/or property damage. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will add sufficient grounding to the steering components. Note: A broken clock spring would result in a driver airbag warning message appearing in the instrument cluster, as well as a red airbag warning lamp illuminating.

### Steering

2017209 11 Apr 2017

On certain vehicles, the steering coupling bolt connection may have been incorrectly torqued. The vibrations during vehicle operation could allow the nut to loosen and come off the retaining bolt. This could lead to a separation of the steering coupling from the steering shaft causing the vehicle to lose the ability to steer which would increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect and torque the steering coupling bolt, as necessary.

### Airbag

2017145 15 Mar 2017

On certain vehicles, an update provided between de 3rd and 5th of December 2016 to the vehicle control unit may have been incorrectly applied. This could affect the proper function of various safety systems such as airbag deployment sequence, seatbelts recognition status, speed limiter setting and others. These conditions could increase the risk of injury to the occupants in the event of a crash. Correction: Dealers will update the affected control units.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

## §3 VALUE [3]

This car asks $14,550[4], $3,560 over the median of $10,990[3].

| | |
|---|---|
| Lowest ask | $4,410 |
| Middle half | $8,999 – $13,722 |
| Median ask | $10,990 |
| This car | $14,550 |

Same model year · 31 live listings · as of 28 Oct 2026

#### OTHER 2013 MERCEDES-BENZ C-CLASS LISTINGS [4]

| | |
|---|---|
| Gatineau, QC · 222,531 km | $4,995 |
| London, ON · 202,994 km | $8,999 |
| Scarborough, ON · 199,600 km | $8,500 |
| Oakville, ON · 72,079 km | $17,888 |
| Toronto, ON · 153,465 km | $10,990 |
| Toronto, ON · 128,850 km | $9,995 |

## §4 EVENTS

2013 **Model year 2013**[1]
Assembly plant Germany

| | |
|---|---|
| 15 Mar 2017 | Transport Canada recall 2017145[2]<br>Issued for the model year · Airbag |
| 11 Apr 2017 | Transport Canada recall 2017209[2]<br>Issued for the model year · Steering |
| 10 Oct 2017 | Transport Canada recall 2017490[2]<br>Issued for the model year · Airbag |
| 20 Dec 2018 | Transport Canada recall 2018724[2]<br>Issued for the model year · Steering |
| 28 Dec 2018 | Transport Canada recall 2018741[2]<br>Issued for the model year · Airbag |
| 16 Aug 2021 | Transport Canada recall 2021514[2]<br>Issued for the model year · Airbag |
| 24 Nov 2025 | Listed for sale, Mississauga, ON[4]<br>VAULT MOTORS · asking $14,550 |
| 25 Oct 2026 | Listing last updated[4]<br>asking $14,550 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 31 live listings, as of 28 Oct 2026
[4] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.