

Register entry, as of 29 October 2026

Listed for sale

Record ID dc421b8e802d

2016 Mercedes-Benz SLK-Class SLK300

2.0 L, 4 cylinders · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD **PK3JA** **2** **G** **F** **120462**

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

SLK-Class · 2.0 L

CHECK 9

Computes

YEAR 10

2016

PLANT 11

Germany

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.0 L, 4 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	SLK-Class	Drive	Not in the decode
Trim	SLK300	Maker	Mercedes-Benz Cars
Body	Convertible	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/slk-class/2016

4 recalls listed by Transport Canada for this model year

Brakes

2017248 10 May 2017

Certain vehicles may have incorrect Electronic Stability Program (ESP) software installed. In the event a driver assist system (e.g. adaptive cruise control) initiates automatic braking and aborts again during the early stage of brake pressure increase, a low residual pressure could remain in the hydraulic brake system. As a result, the braking system could continue applying minimal pressure with the brake pad contacting the rotor, and may heat up when driving is continued. Constant brake pad application over longer periods of driving could lead to the brake fluid heating in the brake caliper, resulting in higher pressure in the brake system. This could reduce brake performance, and increase the risk of a fire causing injury and/or damage to property. Correction: Dealers will update the software for the ESP.

Lights and instruments

2016303 14 Jun 2016

A certain vehicle may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 108 - Lighting System and Retroreflective Devices. The basic setting of the low beam headlamps may deviate from the tolerance range that is required by the standard. Headlight performance could be reduced, potentially increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the basic setting of headlamps, and correct if necessary.

Steering

2016233 17 May 2016

Certain vehicles may have been assembled with improperly manufactured rear tie rod lock nuts. This could cause the rear tie rods to become loose resulting in a change in the alignment, affecting steering control and increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the defective rear tie rod lock nuts.



Electrical

2016156 13 Apr 2016

On certain vehicles, the backup power supply feed for the ignition switch may have been incorrectly connected at the time of production. In the event of a loss of main battery power and an engine stop with the transmission out of park and the electric parking brake not applied, without the backup power supply the transmission would not be able to shift to Park (P). This could result in the vehicle being inoperable without any way of keeping it stationary other than applying the brakes which, under certain circumstances, could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will adapt the wiring harness and update the Software Calibration Number (SCN) coding.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.

Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks \$34,900^[4], the median^[3].



Lowest ask	\$34,900
Middle half	\$34,900 – \$34,900
Median ask	\$34,900
This car	\$34,900

Same model year · 1 live listings · as of 29 Oct 2026

§4 EVENTS

2016	Model year 2016 ^[1] Assembly plant Germany
13 Apr 2016	Transport Canada recall 2016156 ^[2] Issued for the model year · Electrical
17 May 2016	Transport Canada recall 2016233 ^[2] Issued for the model year · Steering
14 Jun 2016	Transport Canada recall 2016303 ^[2] Issued for the model year · Lights and instruments
10 May 2017	Transport Canada recall 2017248 ^[2] Issued for the model year · Brakes
14 Oct 2026	Listed for sale, Vaughan, ON ^[4] Toronto Auto Brokers · asking \$34,900
29 Oct 2026	Listing last updated ^[4] asking \$34,900



§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [3] Cardog market quote, same model year, 1 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 29 Oct 2026 |
-

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

