Register entry, as of 29 October 2026 Listed for sale Record ID 09a8a5c49df7

2020 Mercedes-Benz S-Class S560 4M

4.0 L, 8 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD	UF8GB	3	L	A	524091
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Cars	S-Class · 4.0 L	Computes	2020	Germany	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	4.0 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	S-Class	Drive	Not in the decode
Trim	S560 4M	Maker	Mercedes-Benz Cars
Body	Sedan	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/s-class/2020

5 recalls listed by Transport Canada for this model year

Powertrain

2026168 2 Apr 2026

Issue: On certain vehicles, the driveshaft may not have been manufactured properly. Over time, the driveshaft could wear and the universal joint could break. If this happens, there could be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the driveshaft.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Electrical

2021064 12 Feb 2021

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the communications module may temporarily lose power during a crash. If this happens, the wrong vehicle location may be transmitted through the eCall system. This could cause emergency responders to be sent to the wrong location. Safety Risk: If the eCall system sends out the wrong location after a crash, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Accessories

2021041 1 Feb 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to update the head unit software.

Brakes

2019357 23 Jul 2019

Issue: On certain vehicles equipped with the Driver Assistance Package, a software problem may cause the Active Brake Assist feature not to work properly. This could affect the feature's ability to help reduce or avoid a crash. While the system will still provide audible and visual warnings, the autonomous braking might not occur. Safety Risk: If the brake assist system does not function properly, there could be an increased risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct them to take their vehicle to a dealer to update the radar sensor control unit software.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $49,900[4], $20,000 under the median of $69,900[3].



Lowest ask	$47,898
Middle half	$52,400 – $87,471
Median ask	$69,900
This car	$49,900

Same model year · 6 live listings · as of 29 Oct 2026

OTHER 2020 MERCEDES-BENZ S-CLASS LISTINGS [4]

Oakville, ON · 42,354 km	$89,995

§4 EVENTS

2020	Model year 2020[1] Assembly plant Germany
23 Jul 2019	Transport Canada recall 2019357[2] Issued for the model year · Brakes
1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064[2] Issued for the model year · Electrical
20 May 2022	Transport Canada recall 2022263[2] Issued for the model year · Other

2 Apr 2026	Transport Canada recall 2026168[2] Issued for the model year · Powertrain
25 May 2026	Listed for sale, Vaughan, ON[4] Toronto Auto Brokers · asking $49,900
29 Oct 2026	Listing last updated[4] asking $49,900

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 6 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.