Register entry, as of 29 October 2026 Listed for sale Record ID efe1f1f7e057

# 2017 Mercedes-Benz S-Class AMG S63

5.5 L, 8 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| WDD | UG7JB | 5 | H | A | 313062 |
|---|---|---|---|---|---|
| WMI 1-3 | DESCRIPTOR 4-8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12-17 |
| Mercedes-Benz Cars | S-Class · 5.5 L | Computes | 2017 | Germany | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2017 | Engine | 5.5 L, 8 cylinders |
| Make | Mercedes-Benz | Fuel | Gasoline |
| Model | S-Class | Drive | AWD |
| Trim | AMG S63 | Maker | Mercedes-Benz Cars |
| Body | Sedan | Plant | Germany |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/s-class/2017

**4** recalls listed by Transport Canada for this model year

### Steering — 2018724 — 20 Dec 2018

On certain vehicles originally sold or currently registered in areas of heavy road salt usage during winter months (Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the bolts that attach the electric power steering assist motor to the steering gear housing may corrode and break. This could cause a loss of power steering assist. The resulting increase in steering effort could create the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the mounting bolts and apply a corrosion protection coating to the gear housing and bolts. If the bolts bolt cannot be removed, a replacement steering gear will be installed.

### Structure — 2017642 — 19 Dec 2017

Certain vehicles may fail to conform to Canada Motor Vehicle Safety Standard (CMVSS) 206 – Door Lock and Door Retention Components. The left (driver's side) door locks may indicate a locked position, even when the door is not locked, which is contrary to the requirements of the standard. Correction: Dealers will inspect the left door locks, and replace them as necessary.

### Steering — 2017555 — 15 Nov 2017

On certain vehicles, a bracket for a transistor in the power steering control unit may break due to vibrations and temperature variations during vehicle operation. If the bracket were to break, the control unit may disable the power steering assist, which could unexpectedly increase steering effort, and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the steering rack and replace it, if necessary.

### Seats and restraints

2017205 11 Apr 2017

Certain vehicles may have been equipped with front seat belt pretensioner igniters that do not meet specifications. This could cause the affected pretentioners to fail to deploy properly in the event of a crash (where deployment is warranted), which could increase the risk of injury to vehicle occupants. Correction: Dealers will replace the affected front seat belt pretentioners.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

## §3 VALUE [3]

This car asks $64,999[4], $5,311 over the median of $59,688[3].

| | |
|---|---|
| Lowest ask | $25,995 |
| Middle half | $34,888 – $75,995 |
| Median ask | $59,688 |
| This car | $64,999 |

Same model year · 13 live listings · as of 29 Oct 2026

OTHER 2017 MERCEDES-BENZ S-CLASS LISTINGS [4]

| | |
|---|---|
| Vancouver, BC · 79,500 km | $39,900 |
| Vancouver, BC · 79,500 km | $39,900 |
| Woodbridge, ON · 20,996 km | $92,888 |
| Westbank, BC · 86,422 km | $59,999 |
| Toronto, ON · 117,839 km | $34,888 |
| Vaughan, ON · 73,460 km | $82,900 |

## §4 EVENTS

| | |
|---|---|
| 2017 | Model year 2017[1]<br>Assembly plant Germany |
| 11 Apr 2017 | Transport Canada recall 2017205[2]<br>Issued for the model year · Seats and restraints |
| 15 Nov 2017 | Transport Canada recall 2017555[2]<br>Issued for the model year · Steering |
| 19 Dec 2017 | Transport Canada recall 2017642[2]<br>Issued for the model year · Structure |
| 20 Dec 2018 | Transport Canada recall 2018724[2]<br>Issued for the model year · Steering |
| 27 Apr 2026 | Listed for sale, St-Eustache, QC[4]<br>Empire Auto · asking $64,999 |

| | |
|---|---|
| 28 Oct 2026 | Listing last updated[4]<br>asking $64,999 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We do not collect window stickers for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 13 live listings, as of 29 Oct 2026

[4] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.