Register entry, as of 28 October 2026 Listed for sale Record ID bba95e636748

2018 Mercedes-Benz C-Class AMG C43

3.0 L, 6 cylinders · AWD · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD	WK6EB	3	J	F	666517
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Mercedes-Benz Cars	C-Class · 3.0 L	Computes	2018	Germany	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	C-Class	Drive	AWD
Trim	AMG C43	Maker	Mercedes-Benz Cars
Body	Convertible	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/c-class/2018

18 recalls listed by Transport Canada for this model year

Structure — 2023673 — 15 Dec 2023

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Note: This is an expansion of Transport Canada recall 2021-170. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the front roof panel.

Structure — 2021170 — 22 Mar 2021

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front roof panel.

Seats and restraints — 2021045 — 3 Feb 2021

Issue: On certain C-Class cabriolet models equipped with the PRE-SAFE system, the front seat belts may not retract completely to their storage position. Canadian regulations require seat belts to retract fully when not in use. Safety Risk: If the seat belt does not fully retract, the occupant may find the operation of the seat belt inconvenient and not wear it. This could increase the risk of injury in a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the function of the front seat belt retractors and adjust the dampening foam, if necessary.

Accessories

2021041 1 Feb 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to update the head unit software.

Seats and restraints

2019554 6 Nov 2019

Issue: On certain vehicles, there may be a problem with the front seat belt buckles. This could cause the seat belt warnings to turn on, even if the front seat belts are buckled. If the driver ignores these warnings, the PRE-SAFE and airbag systems may not function properly. Safety Risk: A seat belt pretensioner or airbag system that does not work properly in a crash could increase the risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to check the front seat belt buckles and replace them if necessary.

Electrical

2019398 12 Aug 2019

Issue: On certain vehicles, the 12-volt starter battery may not be properly secured by its mounting bracket. In a crash, the battery may shift and the terminals might disconnect. This could interrupt power to the vehicle, which would affect multiple post-crash systems. It is also possible that the battery could detach from the vehicle. Note: A loose battery could cause rattling or knocking noises from the engine compartment while driving. Safety Risk: A failure of the post-crash systems could increase the risk of injury. A battery that detaches from the vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct them to take their vehicle to a dealer to replace the battery mounting bracket.

12 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/c-class/2018

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $35,985[4], $11,997 over the median of $23,988[3].



Lowest ask	$13,695
Middle half	$19,995 – $30,998
Median ask	$23,988
This car	$35,985

Same model year · 89 live listings · as of 28 Oct 2026

OTHER 2018 MERCEDES-BENZ C-CLASS LISTINGS [4]

Mississauga, ON · 94,351 km	$21,000
Calgary, AB · 168,564 km	$18,977
Windsor, ON · 94,351 km	$22,000
Sault Sainte Marie, ON · 85,515 km	$23,095
Trois-Rivières, QC · 67,329 km	$21,995
Trois-Rivières, QC · 118,113 km	$27,995

§4 EVENTS

2018	Model year 2018[1] Assembly plant Germany
10 Oct 2017	Transport Canada recall 2017490[2] Issued for the model year · Airbag
7 Mar 2018	Transport Canada recall 2018113[2] Issued for the model year · Seats and restraints
4 Apr 2018	Transport Canada recall 2018161[2] Issued for the model year · Seats and restraints
9 Jul 2018	Transport Canada recall 2018370[2] Issued for the model year · Structure
9 Jul 2018	Transport Canada recall 2018368[2] Issued for the model year · Structure
11 Sep 2018	Transport Canada recall 2018488[2] Issued for the model year · Visual system
15 Oct 2018	Transport Canada recall 2018564[2] Issued for the model year · Structure
28 Nov 2018	Transport Canada recall 2018657[2] Issued for the model year · Steering
28 Nov 2018	Transport Canada recall 2018656[2] Issued for the model year · Airbag
28 Nov 2018	Transport Canada recall 2018655[2] Issued for the model year · Seats and restraints
6 Dec 2018	Transport Canada recall 2018685[2] Issued for the model year · Steering
26 Feb 2019	Transport Canada recall 2019091[2] Issued for the model year · Seats and restraints
12 Aug 2019	Transport Canada recall 2019398[2] Issued for the model year · Electrical
6 Nov 2019	Transport Canada recall 2019554[2] Issued for the model year · Seats and restraints
1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
3 Feb 2021	Transport Canada recall 2021045[2] Issued for the model year · Seats and restraints
22 Mar 2021	Transport Canada recall 2021170[2] Issued for the model year · Structure

15 Dec 2023	Transport Canada recall 2023673[2] Issued for the model year · Structure
26 Oct 2026	Listed for sale, Sainte-Rose - Laval, QC[4] Landry Automobiles Dodge Chrysler Jeep Ram · asking $35,985
27 Oct 2026	Listing last updated[4] asking $35,985

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] Cardog market quote, same model year, 89 live listings, as of 28 Oct 2026
[4] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.