

2019 Mercedes-Benz C-Class AMG C43

3.0 L, 6 cylinders · AWD · Convertible · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD WK6EB X K F 861743

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

C-Class · 3.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Germany

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	C-Class	Drive	AWD
Trim	AMG C43	Maker	Mercedes-Benz Cars
Body	Convertible	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/c-class/2019

18 recalls listed by Transport Canada for this model year

Structure

2026364 24 Jul 2026

Issue: On certain vehicles, moisture could enter the driver-side door lock microswitch and cause it to corrode. As a result, the microswitch may fail to automatically engage the parking brake and/or the auto park feature when the door is opened. If this happens, the vehicle could roll away. Note: This problem could also cause the radio and/or interior lights to remain on after exiting the vehicle. Safety Risk: A parked vehicle that rolls away could create the risk of an injury or a crash. Corrective Actions: To reduce the safety risk, Mercedes-Benz recommends that you should always use the parking brake when you park. Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver-side door lock.

Structure

2023673 15 Dec 2023

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Note: This is an expansion of Transport Canada recall 2021-170. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the front roof panel.

Visual system

2022177 12 Apr 2022

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to update the rearview camera software.



Fuel system

2021755 13 Dec 2021

Issue: On certain vehicles, small particles could damage the seals between the fuel rail and fuel injectors. If this happens, there could be a fuel leak in the engine compartment. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel rail and fuel injectors.

Lights and instruments

2021415 5 Jul 2021

Issue: On certain vehicles, a label on the headlamp assembly may contain incorrect information for a service technician. As a result, the headlamps may not get adjusted correctly after a repair. This could cause glare and/or confusion for oncoming drivers. Note: This recall only affects certain vehicles equipped with LED headlamps. Safety Risk: Headlamps that cause glare or confusion for oncoming drivers could increase the risk of a crash. Corrective Action: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the headlamps.

Structure

2021170 22 Mar 2021

Issue: On certain vehicles, the plastic panel located between the windshield and the panoramic sunroof may not have been attached correctly during a prior service repair. Over time, the panel could loosen and separate from the vehicle. Safety Risk: A panel that detaches from a moving vehicle could create a road hazard for others and increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front roof panel.

12 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/c-class/2019

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks \$42,895^[4], \$9,896 over the median of \$32,999^[3].



Lowest ask	\$22,500
Middle half	\$27,999 – \$36,980
Median ask	\$32,999
This car	\$42,895

Same model year · 33 live listings · as of 27 Oct 2026

OTHER 2019 MERCEDES-BENZ C-CLASS LISTINGS [4]

Windsor, ON · 95,000 km	\$36,063
Toronto, ON · 95,000 km	\$36,063
Windsor, ON · 95,000 km	\$36,063
Montréal, QC · 38,915 km	\$27,900
Saint-Laurent, QC · 89,100 km	\$37,995
Burlington, ON · 31,800 km	\$33,888

§4 EVENTS

2019 Model year 2019^[1]
 Assembly plant Germany



28 Nov 2018	Transport Canada recall 2018656 ^[2] Issued for the model year · Airbag
20 Dec 2018	Transport Canada recall 2018725 ^[2] Issued for the model year · Brakes
10 May 2019	Transport Canada recall 2019223 ^[2] Issued for the model year · Engine
12 Aug 2019	Transport Canada recall 2019398 ^[2] Issued for the model year · Electrical
6 Nov 2019	Transport Canada recall 2019554 ^[2] Issued for the model year · Seats and restraints
11 May 2020	Transport Canada recall 2020201 ^[2] Issued for the model year · Label
22 Jun 2020	Transport Canada recall 2020282 ^[2] Issued for the model year · Engine
6 Jul 2020	Transport Canada recall 2020307 ^[2] Issued for the model year · Brakes
1 Feb 2021	Transport Canada recall 2021041 ^[2] Issued for the model year · Accessories
3 Feb 2021	Transport Canada recall 2021045 ^[2] Issued for the model year · Seats and restraints
12 Feb 2021	Transport Canada recall 2021064 ^[2] Issued for the model year · Electrical
3 Mar 2021	Transport Canada recall 2021112 ^[2] Issued for the model year · Other
22 Mar 2021	Transport Canada recall 2021170 ^[2] Issued for the model year · Structure
5 Jul 2021	Transport Canada recall 2021415 ^[2] Issued for the model year · Lights and instruments
13 Dec 2021	Transport Canada recall 2021755 ^[2] Issued for the model year · Fuel system
12 Apr 2022	Transport Canada recall 2022177 ^[2] Issued for the model year · Visual system
15 Dec 2023	Transport Canada recall 2023673 ^[2] Issued for the model year · Structure
24 Jul 2026	Transport Canada recall 2026364 ^[2] Issued for the model year · Structure
26 Oct 2026	Listed for sale, Montréal Nord, QC ^[4] Honda Gabriel · asking \$42,895



27 Oct 2026 Listing last updated^[4]
asking \$42,895

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [3] Cardog market quote, same model year, 33 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [4] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

