Register entry, as of 28 October 2026 Listed for sale Record ID 0e897c2bad37

2019 Mercedes-Benz S-Class AMG S63

4.0 L, 8 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD	XJ8JB	2	K	A	036446
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Cars	S-Class · 4.0 L	Computes	2019	Germany	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	4.0 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	S-Class	Drive	Not in the decode
Trim	AMG S63	Maker	Mercedes-Benz Cars
Body	Coupe	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/s-class/2019

8 recalls listed by Transport Canada for this model year

Powertrain

2026168 2 Apr 2026

Issue: On certain vehicles, the driveshaft may not have been manufactured properly. Over time, the driveshaft could wear and the universal joint could break. If this happens, there could be a loss of power to the wheels. Safety Risk: A loss of power to the wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the driveshaft.

Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Electrical

2021064 12 Feb 2021

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the communications module may temporarily lose power during a crash. If this happens, the wrong vehicle location may be transmitted through the eCall system. This could cause emergency responders to be sent to the wrong location. Safety Risk: If the eCall system sends out the wrong location after a crash, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Accessories

2021041 1 Feb 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to update the head unit software.

Engine

2020121 22 Mar 2020

Issue: On certain S 560 and Maybach S 560 models, the plugs used to close oil ports on the engine could fail. If this happens, oil can leak from the engine. If the engine oil level drops, a red warning message would display in the instrument cluster. If a driver continues to operate the vehicle, the engine could run out of oil and fail. Safety Risk: An oil leak on the road surface could become a hazard for other road users. An engine that fails would result in a sudden loss of engine power. Both of these conditions could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the closure plugs. You should avoid sudden acceleration and driving the vehicle at high engine speeds until the recall repairs are completed. If you detect any of the warnings listed, you should contact a dealership to have your vehicle inspected.

Engine

2020026 24 Jan 2020

Issue: On certain vehicles equipped with a 4.0 liter 8-cylinder gas engine, the oil feed line to the turbochargers could leak. As a result, oil could leak onto hot components in engine compartment. Safety Risk: Oil leaking onto a hot engine components could cause a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to replace the oil feed line to the turbochargers.

2 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/s-class/2019

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $129,995[4], $71,759 over the median of $58,236[3].



Lowest ask	$45,900
Middle half	$53,674 – $91,944
Median ask	$58,236
This car	$129,995

Same model year · 12 live listings · as of 28 Oct 2026

OTHER 2019 MERCEDES-BENZ S-CLASS LISTINGS [4]

Markham, ON · 74,190 km	$54,995
Markham, ON · 45,437 km	$62,995
Calgary, AB · 42,330 km	$79,995
Sarnia, ON · 71,194 km	$50,594
Woodbridge, ON · 44,304 km	$109,888
St-Eustache, QC · 90,563 km	$61,477

§4 EVENTS

2019	Model year 2019[1] Assembly plant Germany
23 Jul 2019	Transport Canada recall 2019357[2] Issued for the model year · Brakes
13 Aug 2019	Transport Canada recall 2019399[2] Issued for the model year · Airbag
24 Jan 2020	Transport Canada recall 2020026[2] Issued for the model year · Engine
22 Mar 2020	Transport Canada recall 2020121[2] Issued for the model year · Engine
1 Feb 2021	Transport Canada recall 2021041[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064[2] Issued for the model year · Electrical
20 May 2022	Transport Canada recall 2022263[2] Issued for the model year · Other
2 Apr 2026	Transport Canada recall 2026168[2] Issued for the model year · Powertrain
21 Sep 2026	Listed for sale, Calgary, AB[4] Lone Star Mercedes-Benz · asking $129,995
28 Oct 2026	Listing last updated[4] asking $129,995

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 12 live listings, as of 28 Oct 2026

[4] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.