

Register entry, as of 26 October 2026

Listed for sale

Record ID b547dd8031cc

# 2018 Mercedes-Benz AMG GT AMG GT R

4.0 L, 8 cylinders · RWD · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**WDD YJ7KA 0 J A 018756**

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

AMG GT · 4.0 L

CHECK 9

Computes

YEAR 10

2018

PLANT 11

Germany

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |               |        |                    |
|------------|---------------|--------|--------------------|
| Model year | 2018          | Engine | 4.0 L, 8 cylinders |
| Make       | Mercedes-Benz | Fuel   | Gasoline           |
| Model      | AMG GT        | Drive  | RWD                |
| Trim       | AMG GT R      | Maker  | Mercedes-Benz Cars |
| Body       | Coupe         | Plant  | Germany            |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/mercedes-benz/amg-gt/2018](https://cardog.app/tools/recalls/mercedes-benz/amg-gt/2018)

## 6 recalls listed by Transport Canada for this model year

### Powertrain

2021402 30 Jun 2021

Issue: On certain vehicles, the driveshaft may detach from the transmission flange. This could cause a loss of power to the drive wheels. Safety Risk: A loss of power to the drive wheels could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct them to take their vehicle to a dealer to inspect, and if necessary, replace the carbon-fiber driveshaft.

### Visual system

2021291 14 May 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

### Electrical

2021185 26 Mar 2021

Issue: On certain vehicles, the power supply cable to the starter may have been attached incorrectly. As a result, the power cable could contact the starter housing. This can damage the cable, and could result in a short circuit. Note: This recall only affects certain AMG E 63 S, GT 63 and GT 63 S models. Safety Risk: A short circuit could cause the vehicle to stall and create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to check the cable connections to the starter and correct them, if necessary.



**Accessories**

2021041 1 Feb 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to update the head unit software.

**Airbag**

2018565 15 Oct 2018

Certain Roadster(convertible) models may have been built with incorrect software in the airbag control unit, and may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 208 – Occupant Protection in Frontal Impacts. In the event of a lower speed crash, this could cause the airbag to deploy with more force than necessary, which could increase the risk of injury for an out-of-position passenger. Correction: Dealers will update and correct the airbag control unit software.

**Seats and restraints**

2017641 19 Dec 2017

On certain vehicles, the seat belt may bind within the seat belt guidance loop. If the seat belt were to bind, a slack in the seat belt may develop, which in the event of a crash, may not restrain the occupant as intended, and increase the risk of injury. Correction: Dealers will remove the spacer disc in the seat belt guidance loop and add an additional sliding component to guide the belt.

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.

Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.

[www.mercedes-benz.ca/en/recalls](http://www.mercedes-benz.ca/en/recalls)

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE** <sup>[4]</sup>

This car asks \$154,888<sup>[5]</sup>, \$29,988 over the median of \$124,900<sup>[4]</sup>.



|             |                       |
|-------------|-----------------------|
| Lowest ask  | \$119,995             |
| Middle half | \$123,900 – \$133,980 |
| Median ask  | \$124,900             |
| This car    | \$154,888             |

Same model year · 5 live listings · as of 26 Oct 2026

**OTHER 2018 MERCEDES-BENZ AMG GT LISTINGS** <sup>[5]</sup>

Toronto, ON · 26,700 km \$133,980

**§4 EVENTS**

|             |                                                                                                    |
|-------------|----------------------------------------------------------------------------------------------------|
| 2018        | Model year 2018 <sup>[1]</sup><br>Assembly plant Germany                                           |
| 19 Dec 2017 | Transport Canada recall 2017641 <sup>[2]</sup><br>Issued for the model year · Seats and restraints |
| 15 Oct 2018 | Transport Canada recall 2018565 <sup>[2]</sup><br>Issued for the model year · Airbag               |
| 1 Feb 2021  | Transport Canada recall 2021041 <sup>[2]</sup><br>Issued for the model year · Accessories          |



|             |                                                                                             |
|-------------|---------------------------------------------------------------------------------------------|
| 26 Mar 2021 | Transport Canada recall 2021185 <sup>[2]</sup><br>Issued for the model year · Electrical    |
| 14 May 2021 | Transport Canada recall 2021291 <sup>[2]</sup><br>Issued for the model year · Visual system |
| 30 Jun 2021 | Transport Canada recall 2021402 <sup>[2]</sup><br>Issued for the model year · Powertrain    |
| 29 Jul 2026 | Listed for sale, Mississauga, ON <sup>[5]</sup><br>B Town Auto Sales · asking \$154,888     |
| 26 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$154,888                                     |

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                              |
|---------------------------------------------------------------------|------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same model year, 5 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 26 Oct 2026                 |
| [3] NHTSA recall records (United States), listed for the model year |                                                                              |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

