

2019 Mercedes-Benz AMG GT AMG GT C

4.0 L, 8 cylinders · RWD · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD YJ8AA 4 K A 023788

WMI 1-3

Mercedes-Benz Cars

DESCRIPTOR 4-8

AMG GT · 4.0 L

CHECK 9

Computes

YEAR 10

2019

PLANT 11

Germany

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	4.0 L, 8 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	AMG GT	Drive	RWD
Trim	AMG GT C	Maker	Mercedes-Benz Cars
Body	Coupe	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/amg-gt/2019

11 recalls listed by Transport Canada for this model year

Electrical

2024342 14 Jun 2024

Issue: On certain vehicles, the recall repairs completed by a Mercedes-Benz dealer during recall 5491309 (Transport Canada recall no. 2022-397) may not have been done correctly. As a result, a second repair is required. On certain vehicles equipped with 4-wheel drive (4Matic), the transmission wiring harness may not be routed correctly. As a result, water could enter the wiring harness connector and cause a short circuit. Note: This recall replaces Transport Canada recall no. 2022-397. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the transmission wiring harness.

Structure

2023601 6 Nov 2023

Issue: On certain vehicles, the center console could unlatch and cause the storage compartment to open in a crash. Safety Risk: A storage compartment that opens in a crash could allow objects to move inside the vehicle, creating a risk of injury. Corrective Actions: Mercedes-Benz will notify owners by mail and advise you to take your vehicle to a dealership to replace the front center console storage compartment.

Electrical

2022397 22 Jul 2022

Issue: On certain vehicles equipped with 4-wheel drive (4Matic), the transmission wiring harness might not be routed correctly. As a result, water could enter the wiring harness connector and cause a short circuit. Safety Risk: A short circuit can create the risk of a fire, even while the vehicle is parked and turned off. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the connector on the transmission wiring harness, and repair it if necessary. Additionally, the dealer will install a bracket to improve the routing of the transmission wiring harness.



Other

2022263 20 May 2022

Issue: On certain vehicles equipped with the emergency calling (eCall) system, the SIM card for the communications module could disable itself. If this happens, the eCall system would not work properly when there is a crash or when the SOS button is pressed. Safety Risk: If the eCall system does not work in an emergency situation, there could be a delay in response from emergency services. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Visual system

2021291 14 May 2021

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the central display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Mercedes-Benz will notify owners by mail and send a wireless over-the-air software update to each vehicle. If the update cannot be completed successfully, you will be notified to schedule an appointment to have the update performed by a dealer.

Electrical

2021185 26 Mar 2021

Issue: On certain vehicles, the power supply cable to the starter may have been attached incorrectly. As a result, the power cable could contact the starter housing. This can damage the cable, and could result in a short circuit. Note: This recall only affects certain AMG E 63 S, GT 63 and GT 63 S models. Safety Risk: A short circuit could cause the vehicle to stall and create the risk of a fire. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct you to take your vehicle to a dealer to check the cable connections to the starter and correct them, if necessary.


5 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/amg-gt/2019

Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
www.mercedes-benz.ca/en/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$148,995^[5], \$16,095 over the median of \$132,900^[4].



Lowest ask	\$115,988
Middle half	\$119,995 – \$138,800
Median ask	\$132,900
This car	\$148,995

Same model year · 5 live listings · as of 29 Oct 2026

OTHER 2019 MERCEDES-BENZ AMG GT LISTINGS [5]

Calgary, AB · 33,904 km	\$169,995
Calgary, AB · 33,610 km	\$119,995
Toronto, ON · 16,000 km	\$138,800

§4 EVENTS

2019 Model year 2019^[1]
Assembly plant Germany



24 Jan 2020	Transport Canada recall 2020026 ^[2] Issued for the model year · Engine
6 Jul 2020	Transport Canada recall 2020307 ^[2] Issued for the model year · Brakes
18 Dec 2020	Transport Canada recall 2020632 ^[2] Issued for the model year · Accessories
1 Feb 2021	Transport Canada recall 2021041 ^[2] Issued for the model year · Accessories
12 Feb 2021	Transport Canada recall 2021064 ^[2] Issued for the model year · Electrical
26 Mar 2021	Transport Canada recall 2021185 ^[2] Issued for the model year · Electrical
14 May 2021	Transport Canada recall 2021291 ^[2] Issued for the model year · Visual system
20 May 2022	Transport Canada recall 2022263 ^[2] Issued for the model year · Other
22 Jul 2022	Transport Canada recall 2022397 ^[2] Issued for the model year · Electrical
6 Nov 2023	Transport Canada recall 2023601 ^[2] Issued for the model year · Structure
14 Jun 2024	Transport Canada recall 2024342 ^[2] Issued for the model year · Electrical
29 Sep 2026	Listed for sale, North Vancouver, BC ^[5] Pacific Honda · asking \$148,995
28 Oct 2026	Listing last updated ^[5] asking \$148,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 5 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |



STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

