Register entry, as of 28 October 2026 Listed for sale Record ID 466b19f0191b

2017 Mercedes-Benz E-Class AMG E43

3.0 L, 6 cylinders · AWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WDD	ZF6EB	7	H	A	246347
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Mercedes-Benz Cars	E-Class · 3.0 L	Computes	2017	Germany	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.0 L, 6 cylinders
Make	Mercedes-Benz	Fuel	Gasoline
Model	E-Class	Drive	AWD
Trim	AMG E43	Maker	Mercedes-Benz Cars
Body	Sedan	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mercedes-benz/e-class/2017

20 recalls listed by Transport Canada for this model year

Airbag — 2021514 — 16 Aug 2021

Issue: On certain vehicles, an incorrect passenger-front airbag may have been installed during a previous repair. As a result, the airbag may not inflate properly in a crash. Safety Risk: An airbag that does not inflate properly can increase the risk of injury in a crash. Corrective Action: Mercedes-Benz will notify owners by mail and instruct you to bring your vehicle to a dealer to replace the passenger-front airbag.

Structure — 2019466 — 23 Sep 2019

Issue: On certain vehicles, the trunk spoiler might not be properly attached. At higher speeds, this could cause the spoiler to detach from the vehicle. Safety Risk: A spoiler that detaches from the vehicle could create a hazard for other drivers and nearby people. Corrective Actions: Mercedes-Benz will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the trunk spoiler and ensure it is properly attached.

Seats and restraints — 2019091 — 26 Feb 2019

Issue: On certain coupe and cabriolet models, the front seatbacks may not fully lock on the right side. In a crash, a seatback that is not properly locked could allow unsecured objects from the rear seats to move forward. Safety Risk: A seatback that is not properly locked could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to inspect front seatbacks and replace them as necessary. Note: This is an expansion of Recall 2018-161.

Airbag

2018741 28 Dec 2018

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag module. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Steering

2018724 20 Dec 2018

On certain vehicles originally sold or currently registered in areas of heavy road salt usage during winter months (Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador), the bolts that attach the electric power steering assist motor to the steering gear housing may corrode and break. This could cause a loss of power steering assist. The resulting increase in steering effort could create the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the mounting bolts and apply a corrosion protection coating to the gear housing and bolts. If the bolts bolt cannot be removed, a replacement steering gear will be installed.

Seats and restraints

2018489 11 Sep 2018

Certain vehicles may have been built with an incorrectly limited passenger seat adjustment range. This could allow the seat to be positioned too far forward, potentially increasing the risk of injury to the seat occupant in the event of a crash. Correction: Dealers will inspect the adjustment range of the passenger seat and install the mechanical adjustment range limiter or update the seat control unit software.

14 more on the model-year record, cardog.app/tools/recalls/mercedes-benz/e-class/2017

> Listed for the model year, not checked against your VIN. Mercedes-Benz confirms which apply.
> Check your VIN with Mercedes-Benz Canada or call a Mercedes-Benz dealer with your VIN.
> www.mercedes-benz.ca/en/recalls

§3 VALUE [3]

This car asks $34,900[4], $8,018 over the median of $26,882[3].

Lowest ask	$14,900
Middle half	$25,242 – $31,447
Median ask	$26,882
This car	$34,900

Same model year · 15 live listings · as of 28 Oct 2026

OTHER 2017 MERCEDES-BENZ E-CLASS LISTINGS [4]

Kitchener, ON · 72,727 km	$31,899
London, ON · 72,727 km	$31,899
Toronto, ON · 185,244 km	$14,900
Georgetown, ON · 72,727 km	$31,899
London, ON · 72,727 km	$31,899
Mississauga, ON · 28,732 km	$26,882

§4 EVENTS

2017	Model year 2017[1] Assembly plant Germany
18 Oct 2016	Transport Canada recall 2016509[2] Issued for the model year · Electrical
15 Nov 2016	Transport Canada recall 2016565[2] Issued for the model year · Structure
9 Feb 2017	Transport Canada recall 2017063[2] Issued for the model year · Powertrain
9 Feb 2017	Transport Canada recall 2017062[2] Issued for the model year · Engine
9 Feb 2017	Transport Canada recall 2017058[2] Issued for the model year · Airbag
9 Feb 2017	Transport Canada recall 2017057[2] Issued for the model year · Airbag
15 Mar 2017	Transport Canada recall 2017142[2] Issued for the model year · Airbag
11 Apr 2017	Transport Canada recall 2017208[2] Issued for the model year · Visual system
11 Apr 2017	Transport Canada recall 2017207[2] Issued for the model year · Steering
11 Apr 2017	Transport Canada recall 2017206[2] Issued for the model year · Airbag
10 Oct 2017	Transport Canada recall 2017490[2] Issued for the model year · Airbag
7 Mar 2018	Transport Canada recall 2018114[2] Issued for the model year · Lights and instruments
4 Apr 2018	Transport Canada recall 2018161[2] Issued for the model year · Seats and restraints
29 Jun 2018	Transport Canada recall 2018354[2] Issued for the model year · Lights and instruments
11 Sep 2018	Transport Canada recall 2018489[2] Issued for the model year · Seats and restraints
20 Dec 2018	Transport Canada recall 2018724[2] Issued for the model year · Steering
28 Dec 2018	Transport Canada recall 2018741[2] Issued for the model year · Airbag

26 Feb 2019	Transport Canada recall 2019091[2] Issued for the model year · Seats and restraints
23 Sep 2019	Transport Canada recall 2019466[2] Issued for the model year · Structure
16 Aug 2021	Transport Canada recall 2021514[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, Calgary, AB[4] Mercedes-Benz Downtown Calgary · asking $34,900
28 Oct 2026	Listing last updated[4] asking $34,900

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] Cardog market quote, same model year, 15 live listings, as of 28 Oct 2026

[4] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.