Register entry, as of 27 October 2026 Listed for sale Record ID 71f141d53002

2017 MINI Clubman

2.0 L, 3 cylinders · Hatchback · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

WMW	LU5C3	6	H	2	E84230
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
MINI · BMW AG	Clubman · 2.0 L	Computes	2017	Germany	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	2.0 L, 3 cylinders
Make	MINI	Fuel	Gasoline
Model	Clubman	Drive	Not in the decode
Trim	Not in the decode	Maker	BMW AG
Body	Hatchback	Plant	Germany

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/mini/clubman/2017

5 recalls listed by Transport Canada for this model year

Label

2024544 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Seats and restraints

2019276 7 Jun 2019

Issue: A problem with the driver's seat belt could cause it not to lock-up as designed during braking or in a crash. Safety Risk: A seat belt that does not lock properly in a crash could cause an increased risk of injury. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to replace the driver's seat belt assembly.

Lights and instruments

2017189 31 Mar 2017

Certain vehicles may fail to comply with the requirements of CMVSS 108 - Lighting System and Retroreflective Devices. The bumper embedded rear inner brake lights turn off when the turn signal light is applied, contrary to requirements of the standard. This could be confusing to a road user located behind the vehicle during simultaneous braking and signalling, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will reprogram the vehicle to correct the non-compliance.

Airbag

2016632 15 Dec 2016

Certain vehicles may have been equipped with airbag inflators that do not meet specifications. This could cause affected airbags to fail to deploy properly in the event of a crash, which could increase the risk of injury to the occupants. Correction: Dealers will replace affected airbag modules. Note: Depending on the vehicle in question, the front passenger, knee, side or curtain airbag modules may be affected.

Airbag

2016369 21 Jul 2016

On certain vehicles, the fabric cover of the side curtain airbags may not have been pre-perforated correctly. This could prevent the airbag from deploying as intended. A side curtain airbag that does not deploy as intended during a crash (where side curtain airbag deployment is warranted) could increase the risk of injury to vehicle occupants. Correction: Dealers will rework the fabric covers of the side curtain airbags.

> Listed for the model year, not checked against your VIN. MINI confirms which apply.
> Check your VIN with MINI Canada or call a MINI dealer with your VIN.
> crm.bmw.ca/en-CA/VehicleRecall

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $17,995[5], $2,000 over the median of $15,995[4].

Lowest ask	$10,900
Middle half	$13,950 – $16,995
Median ask	$15,995
This car	$17,995

Same model year · 5 live listings · as of 27 Oct 2026

OTHER 2017 MINI CLUBMAN LISTINGS [5]

Airdrie, AB · 167,294 km	$10,900

§4 EVENTS

2017	Model year 2017[1] Assembly plant Germany
21 Jul 2016	Transport Canada recall 2016369[2] Issued for the model year · Airbag
15 Dec 2016	Transport Canada recall 2016632[2] Issued for the model year · Airbag
31 Mar 2017	Transport Canada recall 2017189[2] Issued for the model year · Lights and instruments
7 Jun 2019	Transport Canada recall 2019276[2] Issued for the model year · Seats and restraints
15 Aug 2024	Transport Canada recall 2024544[2] Issued for the model year · Label
24 Jan 2026	Listed for sale, Toronto, ON[5] Ryder Auto Sales · asking $17,995
24 Oct 2026	Listing last updated[5] asking $17,995

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 5 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.